

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3335 2080	W578081 150 SEK	Mercedes C-Class -15 Camshaft adjusting valve	C 180 M274.910 5DR KOMBI BENSIN INSUG	Lycksele Bildemontering AB 0950-12140	8.352 A
3335 2080	W578082 150 SEK	Mercedes C-Class -15 Camshaft adjusting valve	C 180 M274.910 5DR KOMBI BENSIN AVGAS	Lycksele Bildemontering AB 0950-12140	8.352 A
4949 2080	W452631 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
4949 2080	W452630 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
4949 2080	W452633 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
4949 2080	W452629 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
4949 2080	W452628 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
4949 2080	W452635 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
4949 2080	W452634 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
4949 2080	W452632 156 SEK	VW Golf, e-Golf -16 Camshaft adjusting valve	GOLF CJSB A 5DR CROSS-OVER BENSIN INSUG, AVGAS	Lycksele Bildemontering AB 0950-12140	1.429 A
5332 2080	W477287 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
5332 2080	W477293 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
5332 2080	W477291 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
5332 2080	W477289 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
5332 2080	W477288 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
5332 2080	W477286 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
5332 2080	W477292 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
5332 2080	W477290 186 SEK	Seat Leon -19 Camshaft adjusting valve	SEAT LEON ST DNUe AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	880 A
1349 2080	W522830 220 SEK	Audi A7 -20 Camshaft adjusting valve	A7 55 TFSI e DLGA AUTOMAT 5DR KOMBI-SEDAN ELHYBRI	Lycksele Bildemontering AB 0950-12140	226 A
1349 2080	W522829 224 SEK	Audi A7 -20 Camshaft adjusting valve	A7 55 TFSI e DLGA AUTOMAT 5DR KOMBI-SEDAN ELHYBRI	Lycksele Bildemontering AB 0950-12140	226 A
1349 2080	W522831 224 SEK	Audi A7 -20 Camshaft adjusting valve	A7 55 TFSI e DLGA AUTOMAT 5DR KOMBI-SEDAN ELHYBRI	Lycksele Bildemontering AB 0950-12140	226 A
5351 2080	W615868 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*
5351 2080	W615870 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*
5351 2080	W615866 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5351 2080	W615871 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*
5351 2080	W615872 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*
5351 2080	W615873 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*
5351 2080	W615867 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*
5351 2080	W615869 250 SEK	Cupra Leon -22 Camshaft adjusting valve	CUPRA LEON DNFB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	2.579 A*
1359 2080	W598360 250 SEK	Audi Q5 -22 Camshaft adjusting valve	Q5 55 TFSI E DRYA AUTOMAT 5DR SUV ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	1.365 A*