

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|--------------------|---|---|--|-------------------|
| 4490 7268 | W614813 500 SEK | Toyota RAV 4 -20 Knock sensor | RAV4 19-8gt;A25A-FXS V 5DR STATIONSVAGN KOMBIVAGN E | Lycksele Bildemontering AB 0950-12140 | 12.720 A |
| 1733 7268 | W614492 325 SEK | Citroen C5 -22 Knock sensor | C5 AIRCROSS HNS AUTOMAT 5DR SUV BENSIN | Lycksele Bildemontering AB 0950-12140 | 320 A |
| 4223 7268 | W613663 562 SEK | Skoda Kamiq -21 Knock sensor Left Front | KAMIQ DLAA AUTOMAT 5DR HALVKOMBI BENSIN VÄNSTER FRAM | Lycksele Bildemontering AB 0950-12140 | 4.122 A |
| 3232 7268 | W612781 625 SEK | Mazda CX-60 -22 Knock sensor | CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN | Lycksele Bildemontering AB 0950-12140 | 1.844 A |
| 2451 7268 | W611103 400 SEK | Ford Mondeo -21 Knock sensor | MONDEO UACC V 5DR STATIONSVAGN KOMBIVAGN ELHYBRID | Lycksele Bildemontering AB 0950-12140 | 9.623 A |
| 2451 7268 | W611104 400 SEK | Ford Mondeo -21 Knock sensor | MONDEO UACC V 5DR STATIONSVAGN KOMBIVAGN ELHYBRID | Lycksele Bildemontering AB 0950-12140 | 9.623 A |
| 5292 7268 | W607249 500 SEK | Hyundai i30 -20 Knock sensor | I 30 G4LD AUTOMAT 5DR KOMBI BENSIN | Lycksele Bildemontering AB 0950-12140 | 2.407 A |
| 4489 7268 | W606778 625 SEK | Toyota Corolla -23 Knock sensor | COROLLA 1,8 | Lycksele Bildemontering AB 0950-12140 | 189 A |
| 4957 7268 | W605130 625 SEK | VW Golf, e-Golf -23 Knock sensor | VOLKSWAGEN, VW DPBA AUTOMAT 5DR STATIONSVAGN KOMBI | Lycksele Bildemontering AB 0950-12140 | 1.231 A |
| 4673 7268 | W601243 500 SEK | Toyota Yaris Cross -22 Knock sensor | YARIS CROSS M15A-FXE V 5DR CROSS-OVER ELHYBRID BEN | Lycksele Bildemontering AB 0950-12140 | 1.830 A |
| 8701 7268 | W600179 350 SEK | Ski-Doo Snöskoter -15 Knock sensor | SUMMIT X 154" 800ETEC | Lycksele Bildemontering AB 0950-12140 | 499 A |
| 4719 7268 | W597831 175 SEK | Mini Cooper Clubman F54 -19 Knock sensor | COOPER CLUBMAN B48-A20A AUTOMAT 5DR KOMBI BENSIN | Lycksele Bildemontering AB 0950-12140 | 4.004 A |
| 4719 7268 | W597830 175 SEK | Mini Cooper Clubman F54 -19 Knock sensor | COOPER CLUBMAN B48-A20A AUTOMAT 5DR KOMBI BENSIN | Lycksele Bildemontering AB 0950-12140 | 4.004 A |
| 8702 7268 | W596821 400 SEK | Lynx Snöskoter -18 Knock sensor | BOOND DS3900 850 E-TEC RADIEN 850ETEC | Lycksele Bildemontering AB 0950-12140 | 963 A |
| 5287 7268 | W596439 438 SEK | Hyundai i20 -22 Knock sensor | I20 G3LE AUTOMAT 5DR KOMBI-SEDAN BENSIN | Lycksele Bildemontering AB 0950-12140 | 900 A |
| 8703 7268 | W595410 400 SEK | Arctic Cat Snöskoter -19 Knock sensor | ASCENDER M6000 | Lycksele Bildemontering AB 0950-12140 | 435 A |
| 8705 7268 | W593753 500 SEK | Polaris Snöskoter -16 Knock sensor | 800 PRO RMK 163 AXYS 800CFI | Lycksele Bildemontering AB 0950-12140 | 160 A |
| 2455 7268 | W592845 162 SEK | Ford Kuga -23 Knock sensor | KUGA BGDC V 5DR SUV ELHYBRID BENSIN | Lycksele Bildemontering AB 0950-12140 | 382 A |
| 5573 7268 | W590746 125 SEK | KIA Sorento -21 Knock sensor | SORENTO G4FT AUTOMAT 5DR SUV ELHYBRID BENSIN | Lycksele Bildemontering AB 0950-12140 | 7.024 A |
| 3335 7268 | W578085 200 SEK | Mercedes C-Class -15 Knock sensor | C 180 M274.910 5DR KOMBI BENSIN | Lycksele Bildemontering AB 0950-12140 | 8.352 A |
| 5576 7268 | W577942 400 SEK | KIA Cee'd, Cee'd SW -23 Knock sensor | CEED G4LE AUTOMAT 5DR KOMBI ELHYBRID BENSIN | Lycksele Bildemontering AB 0950-12140 | 148 A |
| 8702 7268 | W577395 400 SEK | Lynx Snöskoter -11 Knock sensor | COM. LTD 600 E-TEC XU 600ETEC | Lycksele Bildemontering AB 0950-12140 | 904 A |
| 1347 7268 | W573627 562 SEK | Audi A3, S3 -21 Knock sensor | A3 SPORTBACK DPCA MANUELL 5DR KOMBI BENSIN | Lycksele Bildemontering AB 0950-12140 | 1.390 A |
| 8705 7268 | W563729 500 SEK | Polaris Snöskoter -17 Knock sensor | 800 PRO R AXYS 800CFI BOSCH | Lycksele Bildemontering AB 0950-12140 | 260 A |

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|--------------------|---|---|---|-------------------|
| 1353 7268 | W553988 600 SEK | Audi A1 / S1 -19 Knock sensor | A1 SPORTBACK DKRF AUTOMAT 5DR KOMBI-SEDAN BENSIN VEVAXEL | Lycksele Bildmontering AB 0950-12140 | 5.157 A |
| 5576 7268 | W543730 625 SEK | KIA Cee'd, Cee'd SW -20 Knock sensor | CEED GT-LINE GALE AUTOMAT 4DR KOMBI ELHYBRID BENSIN | Lycksele Bildmontering AB 0950-12140 | 1.482 A |
| 8701 7268 | W541906 350 SEK | Ski-Doo Snöskoter -09 Knock sensor | RENEGADE X 600 E 600ETEC | Lycksele Bildmontering AB 0950-12140 | 778 A |
| 8702 7268 | W528293 400 SEK | Lynx Snöskoter -16 Knock sensor | 49 RANGER 600 E-TEC 600ETEC | Lycksele Bildmontering AB 0950-12140 | 1.065 A |
| 8706 7268 | W527302 625 SEK | Yamaha Snöskoter -21 Knock sensor | MOUNTAINMAX MOUNTAIN MAX 800 | Lycksele Bildmontering AB 0950-12140 | 52 A |
| 8701 7268 | W512818 350 SEK | Ski-Doo Snöskoter -13 Knock sensor | SKI-DOO SUMMITX 163" 800 800ETEC 800ETEC | Lycksele Bildmontering AB 0950-12140 | 604 A |