

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|--------------------|-----------------------------|---|--|-------------------|
| 5025 7450 | W629952 100 SEK | Volvo V50 -10 Coil | 1.8i FLEXIFUEL KOMBI 1.8i/B4184S8 5VXL/MTX75 5DR HG TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 28.744 A |
| 5025 7450 | W607371 100 SEK | Volvo V50 -09 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 22.527 A |
| 5025 7450 | W607369 100 SEK | Volvo V50 -09 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 22.527 A |
| 5025 7450 | W607372 100 SEK | Volvo V50 -09 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 22.527 A |
| 5025 7450 | W607370 100 SEK | Volvo V50 -09 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 22.527 A |
| 5024 7450 | W507075 150 SEK | Volvo V50 -07 Coil | 1.8i FLEXIFUEL KOMBI 125HK 1.8i/B4184S8 5VXL/MTX75 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 11.301 A |
| 5024 7450 | W507078 150 SEK | Volvo V50 -07 Coil | 1.8i FLEXIFUEL KOMBI 125HK 1.8i/B4184S8 5VXL/MTX75 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 11.301 A |
| 5024 7450 | W507076 150 SEK | Volvo V50 -07 Coil | 1.8i FLEXIFUEL KOMBI 125HK 1.8i/B4184S8 5VXL/MTX75 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 11.301 A |
| 5024 7450 | W507077 150 SEK | Volvo V50 -07 Coil | 1.8i FLEXIFUEL KOMBI 125HK 1.8i/B4184S8 5VXL/MTX75 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 11.301 A |
| 5025 7450 | W472021 100 SEK | Volvo V50 -08 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL/MTX75 5DR HGV ET TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 16.644 A |
| 5025 7450 | W468093 100 SEK | Volvo V50 -10 Coil | 1.8i FLEXIFUEL KOMBI 1.8i/B4184S8 5VXL/MTX75 5DR HG TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 28.744 A |
| 5025 7450 | W468094 100 SEK | Volvo V50 -10 Coil | 1.8i FLEXIFUEL KOMBI 1.8i/B4184S8 5VXL/MTX75 5DR HG TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 28.744 A |
| 5025 7450 | W432222 100 SEK | Volvo V50 -08 Coil | 1.8F FLEXIFUEL 125HK KOMBI 1.8F/B4184S8 5VXL 5DR CB TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 9.491 A |
| 5025 7450 | W432223 100 SEK | Volvo V50 -08 Coil | 1.8F FLEXIFUEL 125HK KOMBI 1.8F/B4184S8 5VXL 5DR CB TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 9.491 A |
| 5025 7450 | W432220 100 SEK | Volvo V50 -08 Coil | 1.8F FLEXIFUEL 125HK KOMBI 1.8F/B4184S8 5VXL 5DR CB TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 9.491 A |
| 5025 7450 | W432221 100 SEK | Volvo V50 -08 Coil | 1.8F FLEXIFUEL 125HK KOMBI 1.8F/B4184S8 5VXL 5DR CB TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 9.491 A |
| 5052 7450 | W592623 100 SEK | Volvo C30 -08 Coil | 1.8i FLEXIFUEL B4184S8 MANUELL 3DR CC ETANOL E85 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 15.000 A |
| 5052 7450 | W592620 100 SEK | Volvo C30 -08 Coil | 1.8i FLEXIFUEL B4184S8 MANUELL 3DR CC ETANOL E85 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 15.000 A |
| 5052 7450 | W592621 100 SEK | Volvo C30 -08 Coil | 1.8i FLEXIFUEL B4184S8 MANUELL 3DR CC ETANOL E85 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 15.000 A |
| 5052 7450 | W592622 100 SEK | Volvo C30 -08 Coil | 1.8i FLEXIFUEL B4184S8 MANUELL 3DR CC ETANOL E85 TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 15.000 A |
| 5024 7450 | W529196 150 SEK | Volvo V50 -07 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | - A |
| 5024 7450 | W529195 150 SEK | Volvo V50 -07 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | - A |
| 5024 7450 | W529194 150 SEK | Volvo V50 -07 Coil | 1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | - A |
| 5069 7450 | W506525 100 SEK | Volvo S40 04-12 -07 Coil | 1.8i FLEXIFUEL SEDAN 125HK 1.8i/B4184S8 5VXL 4DR SE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 12.059 A |

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|--------------------|-----------------------------|---|--|-------------------|
| 5069 7450 | W506524 | Volvo S40 04-12 -07 Coil | 1.8l FLEXIFUEL SEDAN 125HK 1.8l/B4184S8 5VXL 4DR SE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 12.059 A |
| 5069 7450 | W506523 | Volvo S40 04-12 -07 Coil | 1.8l FLEXIFUEL SEDAN 125HK 1.8l/B4184S8 5VXL 4DR SE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 12.059 A |
| 5069 7450 | W506526 | Volvo S40 04-12 -07 Coil | 1.8l FLEXIFUEL SEDAN 125HK 1.8l/B4184S8 5VXL 4DR SE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 12.059 A |
| 5074 7450 | W459438 | Volvo S40 04-12 -08 Coil | 1.8l FLEXIFUEL 125HK 1.8l/B4184S8 5VXL/MTX75 4DR SE TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 12.431 A |
| 5074 7450 | W459441 | Volvo S40 04-12 -08 Coil | 1.8l FLEXIFUEL 125HK 1.8l/B4184S8 5VXL/MTX75 4DR SE TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 12.431 A |
| 5074 7450 | W459440 | Volvo S40 04-12 -08 Coil | 1.8l FLEXIFUEL 125HK 1.8l/B4184S8 5VXL/MTX75 4DR SE TESTAD, OK | Vimmerby Bildemontering AB 0492-20028 | 12.431 A |