

| VCode<br>PCode | Stock no.<br>Price   | Vehicle<br>Part                         | Vehicle Information<br>Part Information   | Company<br>Phone                         | Milage<br>Quality |
|----------------|----------------------|---|---|--|-------------------|
| 5025<br>7470   | W693813<br>4.000 SEK | Volvo V50 -08<br>Injection Control unit | 2.0D DIESEL KOMBI 136HK 2.0D/D4204T 5VXL 5DR HGV DI<br>VI KAN KODA OM, RING OSS         | Vimmerby Bildemontering AB<br>0492-20028 | 32.000<br>A       |
| 5025<br>7470   | W664083<br>4.000 SEK | Volvo V50 -08<br>Injection Control unit | 2.4I KOMBI 170 HK 2.4I/B5244S4 5VXL 5DR HGV BENSIN<br>VI KAN KODA OM, RING OSS          | Vimmerby Bildemontering AB<br>0492-20028 | 13.245<br>A       |
| 5025<br>7470   | W654299<br>4.000 SEK | Volvo V50 -11<br>Injection Control unit | 1.6D D2 DIESEL KOMBI 114HK 1.6D/D4162T 6VXL 5DR HGV<br>VI KAN KODA OM, RING OSS         | Vimmerby Bildemontering AB<br>0492-20028 | 14.000<br>A       |
| 5025<br>7470   | W608764<br>4.000 SEK | Volvo V50 -08<br>Injection Control unit | 2.4I KOMBI 2.4I/B5244S4 AUTOMAT 5DR HGV BENSIN<br>TESTAD OK                             | Vimmerby Bildemontering AB<br>0492-20028 | 13.991<br>A       |
| 5025<br>7470   | W607955<br>4.000 SEK | Volvo V50 -09<br>Injection Control unit | 1.6D KOMBI 102HK 1.6D/D4164T 5VXL 5DR HGV DIESEL<br>VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB<br>0492-20028 | 18.561<br>A       |
| 5025<br>7470   | W718643<br>4.000 SEK | Volvo V50 -08<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W695415<br>4.000 SEK | Volvo V50 -09<br>Injection Control unit | VI KAN KODA OM RING OSS   | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W691106<br>4.000 SEK | Volvo V50 -11<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W679673<br>4.000 SEK | Volvo V50 -09<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W679713<br>4.000 SEK | Volvo V50 -10<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W671941<br>4.000 SEK | Volvo V50 -09<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W617219<br>4.000 SEK | Volvo V50 -08<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W586735<br>4.000 SEK | Volvo V50 -10<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W586292<br>4.000 SEK | Volvo V50 -09<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W586054<br>4.000 SEK | Volvo V50 -12<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W580476<br>4.000 SEK | Volvo V50 -07<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W579960<br>4.000 SEK | Volvo V50 -12<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W579867<br>4.000 SEK | Volvo V50 -11<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W579922<br>4.000 SEK | Volvo V50 -11<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W573586<br>4.000 SEK | Volvo V50 -11<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W569910<br>4.000 SEK | Volvo V50 -12<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W568168<br>4.000 SEK | Volvo V50 -08<br>Injection Control unit | VI KAN KODA OM, RING OSS! TESTAD OK   | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W568176<br>4.000 SEK | Volvo V50 -12<br>Injection Control unit | VI KAN KODA OM RING OSS   | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W562270<br>4.000 SEK | Volvo V50 -11<br>Injection Control unit | VI KAN KODA OM, RING OSS  | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |

| VCode<br>PCode | Stock no.<br>Price   | Vehicle<br>Part                         | Vehicle Information<br>Part Information | Company<br>Phone                         | Milage<br>Quality |
|----------------|----------------------|---|---|--|-------------------|
| 5025<br>7470   | W562133<br>4.000 SEK | Volvo V50 -08<br>Injection Control unit | VI KAN KODA OM, RING OSS! TESTAD OK     | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W551130<br>4.000 SEK | Volvo V50 -12<br>Injection Control unit | VI KAN KODA OM, RING OSS                | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W551127<br>4.000 SEK | Volvo V50 -11<br>Injection Control unit | VI KAN KODA OM, RING OSS                | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W549349<br>4.000 SEK | Volvo V50 -07<br>Injection Control unit | VI KAN KODA OM, RING OSS! TESTAD OK     | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |
| 5025<br>7470   | W532409<br>4.000 SEK | Volvo V50 -12<br>Injection Control unit | VI KAN KODA OM, RING OSS                | Vimmerby Bildemontering AB<br>0492-20028 | -<br>A            |