

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5464 5076	W778647 712 SEK	Lexus CT -20 Washer pump rear hatch	LEXUS CT 200H 1.8L 2ZR-FXE AUTOMAT 4DR HALVKOMBI E DENSO, 2 STIFT	Kungsåra Bildemontering AB 021-4711100	2.836 A
4555 5076	W776576 188 SEK	Toyota Yaris -16 Washer pump rear hatch	TOYOTA YARIS 15- 1.5L 1NZ-FXE AUTOMAT 5DR K-S ELH	Kungsåra Bildemontering AB 021-4711100	1.285 A
2186 5076	W753964 138 SEK	Nissan X-Trail -17 Washer pump rear hatch	NISSAN X-TRAIL KOMBI 5DR R9M AUTOMAT 5DR SUV DIESEL FÖR KAMERA.	Kungsåra Bildemontering AB 021-4711100	14.821 A
2981 5076	W735558 325 SEK	Jaguar XF -16 Washer pump rear hatch	JAGUAR XF 16- 3.0L 306DT AUTOMAT 4DR SEDAN DIESEL	Kungsåra Bildemontering AB 021-4711100	10.697 A
4674 5076	W730579 500 SEK	Toyota Yaris -20 Washer pump rear hatch	TOYOTA YARIS 15- 1.5L 2NR-FXE AUTOMAT 5DR FORDON	Kungsåra Bildemontering AB 021-4711100	4.797 A
5599 5076	W701441 325 SEK	KIA Sportage -12 Washer pump rear hatch	KIA SPORTAGE 11-15 1.6L G4FD MANUELL 5DR STATIONSV	Kungsåra Bildemontering AB 021-4711100	10.561 A
5599 5076	W671350 375 SEK	KIA Sportage -11 Washer pump rear hatch	KIA SPORTAGE 11-15 2.0L D4HA MANUELL 5DR STATIONSV	Kungsåra Bildemontering AB 021-4711100	32.674 A
4555 5076	W624735 250 SEK	Toyota Yaris -16 Washer pump rear hatch	TOYOTA YARIS 15- 1NR-FE MANUELL 5DR HALVKOMBI BEN	Kungsåra Bildemontering AB 021-4711100	2.403 A
4583 5076	W622746 250 SEK	Toyota Auris -11 Washer pump rear hatch	TOYOTA AURIS 10-12 AUTOMAT 5DR FORDON AVSETT F	Kungsåra Bildemontering AB 021-4711100	6.808 A
4583 5076	W620003 200 SEK	Toyota Auris -12 Washer pump rear hatch	AURIS 1ADFTV MANUELL KOMBI-SEDAN	Kungsåra Bildemontering AB 021-4711100	11.270 A
1520 5076	W606393 200 SEK	BMW 1-Series -09 Washer pump rear hatch	118 2.0D 6V 3D K-S 118D MANUELL 3DR KOMBI-SEDAN DI	Kungsåra Bildemontering AB 021-4711100	14.409 A
4528 5076	W603669 188 SEK	Toyota Yaris -13 Washer pump rear hatch	1,5 HYBRID AUT 5D K-S 1,5 HYBRID AUTOMAT 5DR KOMBI	Kungsåra Bildemontering AB 021-4711100	3.747 A
5599 5076	W557161 275 SEK	KIA Sportage -11 Washer pump rear hatch	1,7 CRDI 6V 5D SUV 1,7 CRDI MANUELL 6V 5DR SUV DIE	Kungsåra Bildemontering AB 021-4711100	12.830 A
4569 5076	W547390 200 SEK	Toyota Avensis -10 Washer pump rear hatch	2,0 AUT 5D KOMBI 2,0 VARIOMATIC 5DR KOMBI BENSIN	Kungsåra Bildemontering AB 021-4711100	7.928 A
4569 5076	W538756 200 SEK	Toyota Avensis -12 Washer pump rear hatch	1,8 AUT 5D KOMBI (UKP) 1,8 CVT 5DR KOMBI BENSIN	Kungsåra Bildemontering AB 021-4711100	8.039 A
1540 5076	W534344 250 SEK	BMW 5-Series -14 Washer pump rear hatch	520D AUT 5D KOMBI 520D TIPTRONIC 5DR KOMBI DIESEL	Kungsåra Bildemontering AB 021-4711100	6.034 A
4528 5076	W504416 500 SEK	Toyota Yaris -13 Washer pump rear hatch	HYBRID 1,5 AUT ACTIVE 5D K-S 1,5 HYBRID VARIATOR 5	Kungsåra Bildemontering AB 021-4711100	2.542 A
4528 5076	W503852 550 SEK	Toyota Yaris -12 Washer pump rear hatch	1,0 5V 5D K-S (FRP) 1,0 5V 5DR KOMBI-SEDAN BENSIN	Kungsåra Bildemontering AB 021-4711100	5.459 A
4024 5076	W444752 180 SEK	Saab 9-5 -04 Washer pump rear hatch	9-5 (I) 2.3 TURBO 5V 5DR KOMBI BENSIN	Kungsåra Bildemontering AB 021-4711100	14.376 A
1520 5076	W406236 200 SEK	BMW 1-Series -07 Washer pump rear hatch	116i 6V 5D K-S 1,6i 6V 5DR KOMBI-SEDAN BENSIN	Kungsåra Bildemontering AB 021-4711100	10.010 A
1520 5076	W406088 200 SEK	BMW 1-Series -09 Washer pump rear hatch	118D 6V 5D K-S 2,0 TDI 6V 5DR KOMBI-SEDAN DIESEL	Kungsåra Bildemontering AB 021-4711100	3.822 A
4503 5076	W216762 500 SEK	Toyota Aygo -08 Washer pump rear hatch	1,0 12V 5V 5D K-S 1,0i 12V 5V COMBISEDAN	Kungsåra Bildemontering AB 021-4711100	124 A