

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5025 7450	W664159 100 SEK	Volvo V50 -11 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 5VXL/MTX75 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.059 A
5025 7450	W664161 100 SEK	Volvo V50 -11 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 5VXL/MTX75 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.059 A
5025 7450	W664160 100 SEK	Volvo V50 -11 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 5VXL/MTX75 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.059 A
5025 7450	W629952 100 SEK	Volvo V50 -10 Coil	1.8I FLEXIFUEL KOMBI 1,8I/B4184S8 5VXL/MTX75 5DR HG TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	28.744 A
5025 7450	W608771 100 SEK	Volvo V50 -08 Coil	2.4I KOMBI 2.4I/B5244S4 AUTOMAT 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.991 A
5025 7450	W608774 100 SEK	Volvo V50 -08 Coil	2.4I KOMBI 2.4I/B5244S4 AUTOMAT 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.991 A
5025 7450	W608772 100 SEK	Volvo V50 -08 Coil	2.4I KOMBI 2.4I/B5244S4 AUTOMAT 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.991 A
5025 7450	W608770 100 SEK	Volvo V50 -08 Coil	2.4I KOMBI 2.4I/B5244S4 AUTOMAT 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.991 A
5025 7450	W608773 100 SEK	Volvo V50 -08 Coil	2.4I KOMBI 2.4I/B5244S4 AUTOMAT 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.991 A
5025 7450	W607372 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
5025 7450	W607369 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
5025 7450	W607370 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
5025 7450	W607371 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
5025 7450	W472021 100 SEK	Volvo V50 -08 Coil	1,8F KOMBI 125HK 1,8F/B4184S8 5VXL/MTX75 5DR HGV ET TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	16.644 A
5025 7450	W468093 100 SEK	Volvo V50 -10 Coil	1.8I FLEXIFUEL KOMBI 1,8I/B4184S8 5VXL/MTX75 5DR HG TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	28.744 A
5025 7450	W468094 100 SEK	Volvo V50 -10 Coil	1.8I FLEXIFUEL KOMBI 1,8I/B4184S8 5VXL/MTX75 5DR HG TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	28.744 A
5025 7450	W432223 100 SEK	Volvo V50 -08 Coil	1,8F FLEXIFUEL 125HK KOMBI 1,8F/B4184S8 5VXL 5DR CB TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.491 A
5025 7450	W432220 100 SEK	Volvo V50 -08 Coil	1,8F FLEXIFUEL 125HK KOMBI 1,8F/B4184S8 5VXL 5DR CB TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.491 A
5025 7450	W432222 100 SEK	Volvo V50 -08 Coil	1,8F FLEXIFUEL 125HK KOMBI 1,8F/B4184S8 5VXL 5DR CB TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.491 A
5025 7450	W432221 100 SEK	Volvo V50 -08 Coil	1,8F FLEXIFUEL 125HK KOMBI 1,8F/B4184S8 5VXL 5DR CB TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.491 A