

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
1520 7842	W674198	BMW 1-Series -07 Dörr Styrenhet	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7842	W674197	BMW 1-Series -07 Dörr Styrenhet	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7842	W651884	BMW 1-Series -07 Dörr Styrenhet	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7842	W651883	BMW 1-Series -07 Dörr Styrenhet	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7842	W636727	BMW 1-Series -11 Dörr Styrenhet	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7842	W636739	BMW 1-Series -11 Dörr Styrenhet	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7842	W635257	BMW 1-Series -09 Dörr Styrenhet	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7842	W635258	BMW 1-Series -09 Dörr Styrenhet	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7842	W546837	BMW 1-Series -11 Dörr Styrenhet	116 2.0D KOMBI-SEDAN 116HK 2.0D/N47D20C 6VXL/GS617D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.313 A
1520 7842	W546830	BMW 1-Series -11 Dörr Styrenhet	116 2.0D KOMBI-SEDAN 116HK 2.0D/N47D20C 6VXL/GS617D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.313 A
1520 7842	W675867	BMW 1-Series -08 Dörr Styrenhet	2.0D 118D KOMBI-SEDAN 143HK 2.0D/N47D20A 6VXL 3DR C V.FRAM TESTAD OK!V.FRAM	Vimmerby Bildemontering AB 0492-20028	22.151 A
1520 7842	W675863	BMW 1-Series -08 Dörr Styrenhet	2.0D 118D KOMBI-SEDAN 143HK 2.0D/N47D20A 6VXL 3DR C H.FRAM TESTAD OK!H.FRAM	Vimmerby Bildemontering AB 0492-20028	22.151 A
1520 7842	W675960	BMW 1-Series -08 Dörr Styrenhet	118 2.0D (E81, E87) 143HK 2.0D/N47-D20A AUTOMAT 5DR V.FRAM TESTAD OK!V.FRAM	Vimmerby Bildemontering AB 0492-20028	25.722 A
1520 7842	W675959	BMW 1-Series -08 Dörr Styrenhet	118 2.0D (E81, E87) 143HK 2.0D/N47-D20A AUTOMAT 5DR H.FRAM TESTAD OK!H.FRAM	Vimmerby Bildemontering AB 0492-20028	25.722 A