

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5060 7059	W96547 120 SEK	Volvo 940 -92 Power steering Pump fixing	3DR, LIKBIL, AUT, 230FB	H&K Bildemontering AB 0141-219822	- A
5013 7059	W2706685 150 SEK	Volvo 240 -92 Power steering Pump fixing	245-883 GL MANUELL 5DR KOMBI BENSIN	Atracco AB - Hedemora 0225-595540	38.847 A
5076 7059	W1736248 175 SEK	Volvo XC60 -17 Power steering Pump fixing	VOLVO XC60 D4 2,4 D5244T21 TRONIC 5DR SUV DIESEL	Ådalens Bildemontering AB 0612-12420	18.750 A*
4551 7059	W36921 195 SEK	Toyota Corolla -96 Power steering Pump fixing	TOYOTA COROLLA 1.6	H&K Bildemontering AB 0141-219822	17.669 A
4551 7059	W96255 100 SEK	Toyota Corolla -96 Power steering Pump fixing	TOYOTA COROLLA 1.6 SPÄNNARE	H&K Bildemontering AB 0141-219822	17.669 A
5060 7059	W1071935 350 SEK	Volvo 940 -91 Power steering Pump fixing	VOLVO 944-852 GL B230FB T 4DR SED BENSIN	Norrbottns Bildemontering AB 0929-70000	30.718 A
3946 7059	W2700728	LandRover Range Rover -10 Power steering Pump fixing	LAND ROVER LS RANGE ROVER SPORT 306DT AUTOMAT 5DR	Atracco AB - Hedemora 0225-595540	24.132 A
1784 7059	W463711	Citroen Jumpy -14 Power steering Pump fixing	JUMPY 2,0 HDI AUT ODR SKP DIESEL	Boets Bildemontering AB 0144-20040	- A
5050 7059	W28456 350 SEK	Volvo 740 -87 Power steering Pump fixing	VOLVO 744-842 B230E M47 4DR BENSIN	Fornåsa Bildemontering AB 013-103103	35.047 A
5060 7059	W2695430	Volvo 940 -93 Power steering Pump fixing	940-SERIE B230FD 5DR BENSIN	Atracco AB - Hedemora 0225-595540	51.271 A
5051 7059	W28409 350 SEK	Volvo 740 -90 Power steering Pump fixing	B230F M47	Fornåsa Bildemontering AB 013-103103	32.475 A
4024 7059	W92356 99 SEK	Saab 9-5 -01 Power steering Pump fixing	SAAB 9-5 2.0T	H&K Bildemontering AB 0141-219822	26.840 A
2194 7059	W28218 250 SEK	Nissan Navara -02 Power steering Pump fixing	NISSAN KING CAB NAVARA 2 TD25TI T ODR DIESEL	Fornåsa Bildemontering AB 013-103103	19.587 A
5050 7059	W28185 350 SEK	Volvo 740 -87 Power steering Pump fixing	B230E M	Fornåsa Bildemontering AB 013-103103	27.451 A
5051 7059	W28115 350 SEK	Volvo 740 -92 Power steering Pump fixing	VOLVO 745-883 GL B230F REGINA M 5DR BENSIN	Fornåsa Bildemontering AB 013-103103	36.102 A
2958 7059	W462867 670 SEK	Iveco Daily -08 Power steering Pump fixing	DAILY 2.3 HPI 5 VXL ODR SKP DIESEL	Boets Bildemontering AB 0144-20040	- A
5060 7059	W28013 350 SEK	Volvo 940 -94 Power steering Pump fixing	VOLVO 944-833 GL B230FD M 4DR BENSIN	Fornåsa Bildemontering AB 013-103103	- A
3847 7059	W94787 250 SEK	Renault Scenic, Grand Scenic -03 Power steering Pump fixing	RENAULT SCÉNIC I	H&K Bildemontering AB 0141-219822	14.677 A
5051 7059	W27957	Volvo 740 -92 Power steering Pump fixing	VOLVO 745-883 GL/SE-PKT B230F REGINA M 5DR BENSIN	Fornåsa Bildemontering AB 013-103103	49.089 A
5063 7059	W1064503 295 SEK	Volvo V70 -13 Power steering Pump fixing	VOLVO V70 D4162T A 5DR CBI DIESEL KONSOL	Norrbottns Bildemontering AB 0929-70000	19.720 A
5077 7059	W1064642 295 SEK	Volvo V60 -11 Power steering Pump fixing	VOLVO V60 T6 AWD B6304T4 A 5DR CBI BENSIN KONSOL	Norrbottns Bildemontering AB 0929-70000	12.752 A
5064 7059	W1064204 295 SEK	Volvo V70 -15 Power steering Pump fixing	VOLVO V70 D5244T12 A 5DR CBI DIESEL KONSOL	Norrbottns Bildemontering AB 0929-70000	17.253 A
5567 7059	W90540 250 SEK	KIA Carens -06 Power steering Pump fixing	KIA CARENS 2.0	H&K Bildemontering AB 0141-219822	24.265 A
5083 7059	W1181562 412 SEK	Volvo XC70 -13 Power steering Pump fixing	1 XC70 D5244T17 M 5DR CBI DIESEL	Allbildelar i Huddinge AB 010-4974200	16.158 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
1318 7059	W67113001	Audi A4, S4 -02 Power steering Pump fixing		AB Svenssons Bildemontering 044-244117	28.337 A
5055 7059	W2678765	Volvo 850 -97 Power steering Pump fixing	L + 850 B5254S MANUELL 5DR KOMBI BENSIN	Atracco AB - Hedemora 0225-595540	27.592 A
5070 7059	W40115 175 SEK	Volvo S40, V40 96-04 -99 Power steering Pump fixing	VOLVO V40 1.8	H&K Bildemontering AB 0141-219822	38.436 A
5063 7059	W1062137 295 SEK	Volvo V70 -12 Power steering Pump fixing	VOLVO V70 D5204T3 A 5DR CBI DIESEL KONSOL	Norbottens Bildemontering AB 0929-70000	22.995 A*
5052 7059	W2081218 412 SEK	Volvo C30 -08 Power steering Pump fixing	1 C30 2.4 AU B5244S4 AW55-50/51SN 3DR CSE BENSIN	Jönköpings Bildemontering AB 010-4975900	9.390 A
5051 7059	W2676362 175 SEK	Volvo 740 -90 Power steering Pump fixing	745-886 GL/T-PKT B230F Z 5DR KOMBI BENSIN	Atracco AB - Hedemora 0225-595540	0 A