

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3428 3007	W599495	Mitsubishi ASX -13 Handle exterior Left	1.8DI-D DIESEL SUV 116HK 1.8DI/4N13 6VXL 5DR SUV D V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	13.473 A
3428 3007	W599494	Mitsubishi ASX -13 Handle exterior Left	1.8DI-D DIESEL SUV 116HK 1.8DI/4N13 6VXL 5DR SUV D V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	13.473 A
3428 3007	W591175	Mitsubishi ASX -11 Handle exterior Left	1.8DI-D DIESEL 4WD SUV 150HK 1.8DI/4N13 6VXL 5DR SUV V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	15.700 A
3428 3007	W591176	Mitsubishi ASX -11 Handle exterior Left	1.8DI-D DIESEL 4WD SUV 150HK 1.8DI/4N13 6VXL 5DR SUV V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	15.700 A
3428 3007	W578545	Mitsubishi ASX -11 Handle exterior Left	1.6I 117HK SUV 1.6I/4A92 5VXL 5DR SUV BENSIN V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	11.900 A
3428 3007	W578547	Mitsubishi ASX -11 Handle exterior Left	1.6I 117HK SUV 1.6I/4A92 5VXL 5DR SUV BENSIN V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	11.900 A
3428 3007	W527535	Mitsubishi ASX -12 Handle exterior Left	1.8DI-D DIESEL 4WD 116HK 1.8DI/4N13 6VXL/W6MBA 5DR V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	9.619 A
3428 3007	W527537	Mitsubishi ASX -12 Handle exterior Left	1.8DI-D DIESEL 4WD 116HK 1.8DI/4N13 6VXL/W6MBA 5DR V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	9.619 A
3428 3007	W451073	Mitsubishi ASX -11 Handle exterior Left	1.6I/4A92 5VXL 5DR SUV BENSIN V.FRAM V.FRAM	Vimmerby Bildemontering AB 0492-20028	9.080 A
3428 3007	W451080	Mitsubishi ASX -11 Handle exterior Left	1.6I/4A92 5VXL 5DR SUV BENSIN V.BAK TESTAD, OK V.BAK	Vimmerby Bildemontering AB 0492-20028	9.080 A