

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4984 7031	W607250 900 SEK	VW Tiguan -14 Steering stem bearing house Left	1.4TSI 4-MOTION SUV 160HK 1.4TSI/CTHD 6VXL 5DR SUV B TESTAD OK	Vimmerby Bildemontering AB 0492-20028	21.674 A
4984 7031	W559669 1.000 SEK	VW Tiguan -08 Steering stem bearing house Left	2.0TDI 4-MOTION SUV 140HK 2.0TDI/CBAB AUTOMAT7JBG 5 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.856 A
4984 7031	W543865 900 SEK	VW Tiguan -09 Steering stem bearing house Left	1.4TSI 4-MOTION SUV 150HK 1.4TSI/CAVA 6VXL/LMX 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.872 A
4984 7031	W503063 900 SEK	VW Tiguan -10 Steering stem bearing house Left	2.0TDI 4-MOTION 170HK 2.0TDI/CBBB 6VXL/LMU 5DR SUV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.673 A
4984 7031	W493791 1.000 SEK	VW Tiguan -11 Steering stem bearing house Left	1.4TSI 4-MOTION 150HK 1.4TSI/CAVA 6VXL/LMX 5DR SUV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.487 A
4984 7031	W482644 900 SEK	VW Tiguan -10 Steering stem bearing house Left	2.0TDI 4-MOTION 140HK 2.0TDI/CBAB AUTOMAT/AQ450 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	21.928 A
4984 7031	W361426 900 SEK	VW Tiguan -10 Steering stem bearing house Left	2.0TDI 4-MOTION 140HK SUV 2.0TDI/CBAB 6VXL/LMU 5D ABS GIVARE	Vimmerby Bildemontering AB 0492-20028	10.674 A
4984 7031	W675326	VW Tiguan -15 Steering stem bearing house Left	1.4TSI 4-MOTION SUV 160HK 1.4TSI/CTHD 6VXL 5DR SUV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.000 A
4984 7031	W615272	VW Tiguan -11 Steering stem bearing house Left	1.4TSI 4-MOTION SUV 150HK 1.4TSI/CAVA 6VXL 5DR SUV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.800 A
4984 7031	W614438	VW Tiguan -09 Steering stem bearing house Left	2.0TFSI 4-MOTION SUV 170HK 2.0TFSI/CAVA 6VXL/LMW 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	24.619 A
4984 7031	W614334	VW Tiguan -13 Steering stem bearing house Left	2.0TDI 4-MOTION SUV 140HK 2.0TDI/CFFB AUTOMAT 5DR S TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.067 A
4984 7031	W611141	VW Tiguan -08 Steering stem bearing house Left	1.4TSI 4-MOTION SUV 150HK 1.4TSI/BVK 6VXL 5DR SUV BE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	21.132 A