

| VCode<br>PCode | Stock no.<br>Price   | Vehicle<br>Part                           | Vehicle Information<br>Part Information                           | Company<br>Phone                         | Milage<br>Quality |
|----------------|----------------------|---|---|--|-------------------|
| 1322<br>7051   | W641002<br>1.500 SEK | Audi A4, S4 -10<br>Drive shaft Left Front | 1.8TFSI AVANT 160HK 1.8TFSI/CDHB 6VXL 5DR HGV BENSI<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 20.619<br>A       |
| 1322<br>7051   | W558102<br>1.500 SEK | Audi A4, S4 -09<br>Drive shaft Left Front | 2.0TDI DIESEL AVANT 170HK 2.0TDI/CAHA 6VXL/UST 5DR<br>TESTAD OK   | Vimmerby Bildemontering AB<br>0492-20028 | 21.111<br>A       |
| 1322<br>7051   | W555900<br>1.500 SEK | Audi A4, S4 -12<br>Drive shaft Left Front | 2.0TDI DIESEL AVANT 136HK 2.0TDI/CJCB 6VXL/LLM 5DR<br>TESTAD OK   | Vimmerby Bildemontering AB<br>0492-20028 | 18.341<br>A       |
| 1322<br>7051   | W547541<br>1.500 SEK | Audi A4, S4 -08<br>Drive shaft Left Front | 3.0D TDI DIESEL QUATTRO 239HK 3.0TDI/CAPA 6VXL/KMU<br>TESTAD, OK  | Vimmerby Bildemontering AB<br>0492-20028 | 24.130<br>A       |
| 1322<br>7051   | W534314<br>1.500 SEK | Audi A4, S4 -11<br>Drive shaft Left Front | 2.0TDI SEDAN 136HK 2.0TDI/CAGB 6VXL/LLM 4DR SED DIE<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 18.335<br>A       |
| 1322<br>7051   | W716122<br>1.500 SEK | Audi A4, S4 -11<br>Drive shaft Left Front | 1.8TFSI QUATTRO AVANT 160HK 1.8TFSI/CDHB 6VXL 5DR H<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 22.000<br>A       |
| 1322<br>7051   | W640469<br>1.500 SEK | Audi A4, S4 -08<br>Drive shaft Left Front | 1.8TFSI SEDAN 160HK 1.8TFSI/CABB 6VXL 4DR SED BENSI<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 19.903<br>A       |
| 1322<br>7051   | W639975<br>1.500 SEK | Audi A4, S4 -09<br>Drive shaft Left Front | 1.8TFSI AVANT 160HK 1.8TFSI/CDHB VARIOMATIC 5DR HGV<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 23.000<br>A       |
| 1322<br>7051   | W639174<br>1.500 SEK | Audi A4, S4 -10<br>Drive shaft Left Front | 1.8TFSI AVANT 120HK 1.8TFSI/CDHA 6VXL/LLV 5DR HGV BE<br>TESTAD OK | Vimmerby Bildemontering AB<br>0492-20028 | 21.284<br>A       |
| 1322<br>7051   | W615550<br>1.500 SEK | Audi A4, S4 -09<br>Drive shaft Left Front | 1.8TFSI AVANT 160HK 1.8TFSI/CDHB 6VXL 5DR HGV BENSI<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 20.000<br>A       |
| 1322<br>7051   | W599821<br>1.500 SEK | Audi A4, S4 -11<br>Drive shaft Left Front | 2.0TDI QUATTRO AVANT 143HK 2.0TDI/CAGA 6VXL 5DR CBI<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 24.837<br>A       |
| 1322<br>7051   | W597334<br>1.500 SEK | Audi A4, S4 -09<br>Drive shaft Left Front | 2.0TDI DIESEL AVANT 170HK 2.0TDI/CAHA 6VXL 5DR DIES<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 23.106<br>A       |
| 1322<br>7051   | W587105<br>1.500 SEK | Audi A4, S4 -09<br>Drive shaft Left Front | 1.8TFSI SEDAN 160HK 1.8TFSI/CDHB VARIOMATIC 4DR SED<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 21.695<br>A       |
| 1322<br>7051   | W582584<br>1.500 SEK | Audi A4, S4 -11<br>Drive shaft Left Front | 2.0TFSI FLEXIFUEL SEDAN 180HK 2.0TFSI/CFKA 6VXL 4DR<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 17.100<br>A       |
| 1322<br>7051   | W571854<br>1.500 SEK | Audi A4, S4 -09<br>Drive shaft Left Front | 2.0TFSI SEDAN 180HK 2.0TFSI/CDNB 6VXL/KBZ 4DR SED B<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 13.988<br>A       |
| 1322<br>7051   | W571396<br>1.500 SEK | Audi A4, S4 -11<br>Drive shaft Left Front | 2.0TFSI FLEXIFUEL QUATTRO 180H 2.0TFSI/CFKA 6VXL/LR<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 13.933<br>A       |
| 1322<br>7051   | W570156<br>1.500 SEK | Audi A4, S4 -09<br>Drive shaft Left Front | 3.0TDI DIESEL QUATTRO 239HK 3.0TDI/CAPA 6VXL/KMU 5D<br>TESTAD OK  | Vimmerby Bildemontering AB<br>0492-20028 | 23.741<br>A       |