

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|----------------------|------------------------------------------------|--------------------------------------------------------------------------------------------|------------------------------------------|-------------------|
| 1707 7470 | W647569 4.000 SEK | Citroen Berlingo -18 Injection Control unit | 1.6HDI DIESEL SKÅP 99HK 1.6HDI/BHY AUTOMAT 5DR SKP VI KAN KODA OM, RING OSS! | Vimmerby Bildemontering AB 0492-20028 | 1.826 A |
| 1707 7470 | W610260 4.000 SEK | Citroen Berlingo -18 Injection Control unit | 1.6HDI DIESEL SKÅP 99HK 1.6HDI/BHY 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 2.959 A |
| 1707 7470 | W596405 4.000 SEK | Citroen Berlingo -16 Injection Control unit | 1.6HDI SKÅP 99HK 1.6HDI/BHY 5VXL 5DR SKP DIESEL TESTAD OK! | Vimmerby Bildemontering AB 0492-20028 | 7.965 A |
| 1707 7470 | W593547 4.000 SEK | Citroen Berlingo -14 Injection Control unit | 1.6HDI DIESEL FAMILY 90HK 1.6HDI/9HF 5VXL 5DR DIESE VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 7.328 A |
| 1707 7470 | W593595 4.000 SEK | Citroen Berlingo -14 Injection Control unit | 1.6HDI DIESEL SKÅP 90HK 1.6HDI/9HF 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 6.997 A |
| 1707 7470 | W592687 4.000 SEK | Citroen Berlingo -13 Injection Control unit | 1.6HDI SKÅP 90HK 1.6HDI/9HF 5VXL 5DR SKP DIESEL VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 8.653 A |
| 1707 7470 | W575125 4.000 SEK | Citroen Berlingo -16 Injection Control unit | 1.6HDI 99HK 1.6HDI/BHY 5VXL 5DR SKP DIESEL MAPPAD, STARTSPÄRR AV 5VXL | Vimmerby Bildemontering AB 0492-20028 | 2.555 A |
| 1707 7470 | W569551 4.000 SEK | Citroen Berlingo -15 Injection Control unit | 1.6HDI DIESEL SKÅP 90HK 1.6HDI/9HF 5VXL 5DR SKP DIE TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 5.771 A |
| 1707 7470 | W568975 4.000 SEK | Citroen Berlingo -17 Injection Control unit | 1.6HDI DIESEL 99HK 1.6HDI/BHY 5VXL 5DR SKP DIESEL TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 3.105 A |
| 1707 7470 | W529825 3.750 SEK | Citroen Berlingo -13 Injection Control unit | 1.6HDI DIESEL SKÅP 75HK 1.6HDI/9HN 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 4.804 A |
| 1707 7470 | W498236 3.750 SEK | Citroen Berlingo -12 Injection Control unit | 1.6HDI 90HK 1.6HDI/9HF 5VXL 5DR SKP DIESEL VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 8.247 A |
| 1707 7470 | W478537 3.750 SEK | Citroen Berlingo -12 Injection Control unit | 1.6HDI 90HK SKÅP 1.9HDI/9HF AUTOMAT 5DR SKP DIESEL VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 9.451 A |
| 1707 7470 | W459079 3.750 SEK | Citroen Berlingo -11 Injection Control unit | 1.6HDI SKÅP 90HK 1.6HDI/9HS 5VXL 5DR SKP DIESEL VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 10.069 A |
| 1707 7470 | W451274 4.000 SEK | Citroen Berlingo -15 Injection Control unit | 1.6HDI 90HK 1.6HDI/9HF 5VXL 5DR SKP DIESEL VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 1.045 A |
| 1707 7470 | W425497 3.750 SEK | Citroen Berlingo -08 Injection Control unit | 1.6HDI 90HK SKÅP 1.6HDI/9HX 5VXL 5DR SKP DIESEL VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 7.273 A |
| 1707 7470 | W419954 3.750 SEK | Citroen Berlingo -11 Injection Control unit | 1.6HDI SKÅP 1.6HDI/9HS 5VXL 5DR SKP DIESEL VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 7.705 A |
| 1707 7470 | W731490 | Citroen Berlingo -15 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 90HK 1.6/9HF 5VXL 5DR SKP D VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 10.565 A |
| 1707 7470 | W731072 | Citroen Berlingo -15 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 75HK 1.6HDI/9HN 5VXL 5DR SK VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 12.224 A |
| 1707 7470 | W730934 | Citroen Berlingo -17 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 99HK 1.6/BHY 5VXL 5DR SKP D VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 7.205 A |
| 1707 7470 | W714663 | Citroen Berlingo -12 Injection Control unit | 1.6HDI DIESEL SKÅP 90HK 1.6HDI/9HF 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 14.900 A |
| 1707 7470 | W714656 | Citroen Berlingo -14 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 90HK 1.6/9HF 5VXL 5DR SKP D VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 16.228 A |
| 1707 7470 | W714677 | Citroen Berlingo -10 Injection Control unit | 1.6HDI SKÅP 75HK 1.6HDI/9HT 5VXL 5DR SKP DIESEL TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 13.300 A |
| 1707 7470 | W714644 | Citroen Berlingo -08 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 75HK 1.6/9HT 5VXL 5DR SKP D VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 17.212 A |
| 1707 7470 | W712008 | Citroen Berlingo -12 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 90HK 1.6HDI/9HF 5VXL 5DR SK VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 21.617 A |

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|----------------------|------------------------------------------------|----------------------------------------------------------------------------------|------------------------------------------|-------------------|
| 1707 7470 | W701923 | Citroen Berlingo -13 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 75HK 1.6HDI/9HN 5VXL SKP DI VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 14.921 A |
| 1707 7470 | W701925 | Citroen Berlingo -09 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 90HK 1.6HDI/9HS 5VXL SKP DI VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 13.744 A |
| 1707 7470 | W665286 | Citroen Berlingo -10 Injection Control unit | 1.6HDI DIESEL SKÅP 90HK 1.6HDI/9HS 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 20.500 A |
| 1707 7470 | W665269 | Citroen Berlingo -12 Injection Control unit | 1.6HDI DIESEL 90HK 1.6HDI/9HF 5VXL 5DR SKP DIESEL VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | 24.400 A |
| 1707 7470 | W714671 | Citroen Berlingo -15 Injection Control unit | 1.6HDI DIESEL SKÅP 90HK 1.6HDI/9HF 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W711999 | Citroen Berlingo -14 Injection Control unit | 1.6HDI DIESEL SKÅP 90HK 1.6DI/9HF 5VXL 5DR SKP DIES VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W665288 | Citroen Berlingo -11 Injection Control unit | 1.6HDI DIESEL SKÅP 90HK 1.6HDI/9HS 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W665289 | Citroen Berlingo -10 Injection Control unit | 1.6HDI DIESEL SKÅP 75HK 1.6HDI/9HT 5VXL 5DR SKP DIE VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W668726 | Citroen Berlingo -11 Injection Control unit | 1.6 HDI DIESEL MINIFLEX 90HK 1.6HDI/9HS 5VXL 5DR SK VI KAN KODA OM, RING OSS! | Vimmerby Bildemontering AB 0492-20028 | 25.000 A |
| 1707 7470 | W600491 4.000 SEK | Citroen Berlingo -18 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W587438 4.000 SEK | Citroen Berlingo -15 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W584832 3.750 SEK | Citroen Berlingo -11 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W579820 3.750 SEK | Citroen Berlingo -14 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W579824 3.750 SEK | Citroen Berlingo -11 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W579822 3.750 SEK | Citroen Berlingo -13 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W579836 4.000 SEK | Citroen Berlingo -15 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W577327 3.750 SEK | Citroen Berlingo -10 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W573587 3.750 SEK | Citroen Berlingo -08 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W571219 4.000 SEK | Citroen Berlingo -15 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W571205 3.750 SEK | Citroen Berlingo -08 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W571214 3.750 SEK | Citroen Berlingo -13 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W571225 4.000 SEK | Citroen Berlingo -15 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W562240 3.750 SEK | Citroen Berlingo -08 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W554582 4.000 SEK | Citroen Berlingo -15 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|----------------------|------------------------------------------------|-----------------------------------------|------------------------------------------|-------------------|
| 1707 7470 | W554593 4.000 SEK | Citroen Berlingo -15 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W547664 4.000 SEK | Citroen Berlingo -10 Injection Control unit | VI KODAR OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W547367 4.000 SEK | Citroen Berlingo -14 Injection Control unit | RING OSS, VID KODAR OM | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W546647 3.750 SEK | Citroen Berlingo -09 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W546646 4.000 SEK | Citroen Berlingo -14 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W538396 3.750 SEK | Citroen Berlingo -08 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W538397 4.000 SEK | Citroen Berlingo -10 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W538393 4.000 SEK | Citroen Berlingo -14 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W538400 3.750 SEK | Citroen Berlingo -08 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W538395 4.000 SEK | Citroen Berlingo -14 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W532430 4.000 SEK | Citroen Berlingo -14 Injection Control unit | VI KAN KODA OM, RING OSS | Vimmerby Bildemontering AB 0492-20028 | - A |
| 1707 7470 | W522822 4.000 SEK | Citroen Berlingo -12 Injection Control unit | VI KAN KODA OM, RING OSS! TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | - A |