

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5063 7450	W695166 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 6VXL 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	12.521 A
5063 7450	W695165 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 6VXL 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	12.521 A
5063 7450	W695164 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 6VXL 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	12.521 A
5063 7450	W695167 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 6VXL 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	12.521 A
5025 7450	W664161 100 SEK	Volvo V50 -11 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 5VXL/MTX75 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.059 A
5025 7450	W664160 100 SEK	Volvo V50 -11 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 5VXL/MTX75 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.059 A
5025 7450	W664159 100 SEK	Volvo V50 -11 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 5VXL/MTX75 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.059 A
5063 7450	W635344 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.000 A
5063 7450	W635343 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.000 A
5063 7450	W635342 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.000 A
5063 7450	W635341 120 SEK	Volvo V70 -10 Coil	2.0F FLEXIFUEL KOMBI 146HK 2.0F/B4204S4 AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.000 A
5025 7450	W629952 100 SEK	Volvo V50 -10 Coil	1.8I FLEXIFUEL KOMBI 1.8I/B4184S8 5VXL/MTX75 5DR HG TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	28.744 A
5025 7450	W607369 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
5025 7450	W607372 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
5025 7450	W607371 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
5025 7450	W607370 100 SEK	Volvo V50 -09 Coil	1.8F KOMBI 125HK 1.8F/B4184S8 5VXL 5DR HGV ETANOLE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.527 A
2427 7450	W556424 200 SEK	Ford Focus -07 Coil	1.8F KOMBI-SEDAN 125HK 1.8F/Q7DA 5VXL 5DR CC ETANOL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.087 A
2427 7450	W556423 200 SEK	Ford Focus -07 Coil	1.8F KOMBI-SEDAN 125HK 1.8F/Q7DA 5VXL 5DR CC ETANOL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.087 A
2427 7450	W556421 200 SEK	Ford Focus -07 Coil	1.8F KOMBI-SEDAN 125HK 1.8F/Q7DA 5VXL 5DR CC ETANOL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.087 A
5024 7450	W530204 150 SEK	Volvo V50 -05 Coil	1.8I KOMBI 125HK 1.8I/B4184S11 5VXL 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	23.369 A
5024 7450	W530311 150 SEK	Volvo V50 -04 Coil	1.8 KOMBI 125HK 1.8/B4184S11 5VXL HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	29.665 A
5024 7450	W530312 150 SEK	Volvo V50 -04 Coil	1.8 KOMBI 125HK 1.8/B4184S11 5VXL HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	29.665 A
5024 7450	W530308 150 SEK	Volvo V50 -04 Coil	1.8 KOMBI 125HK 1.8/B4184S11 5VXL HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	29.665 A
5024 7450	W530206 150 SEK	Volvo V50 -05 Coil	1.8I KOMBI 125HK 1.8I/B4184S11 5VXL 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	23.369 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5024 7450	W530203 150 SEK	Volvo V50 -05 Coil	1.8I KOMBI 125HK 1.8I/B4184S11 5VXL 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	23.369 A
5024 7450	W530310 150 SEK	Volvo V50 -04 Coil	1.8 KOMBI 125HK 1.8I/B4184S11 5VXL HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	29.665 A
5024 7450	W530078 150 SEK	Volvo V50 -06 Coil	1,8 KOMBI 125HK 1,8I/B4184S11 5VXL/MTX75 5DR HGV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.105 A
5024 7450	W530079 150 SEK	Volvo V50 -06 Coil	1,8 KOMBI 125HK 1,8I/B4184S11 5VXL/MTX75 5DR HGV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.105 A
5024 7450	W530077 150 SEK	Volvo V50 -06 Coil	1,8 KOMBI 125HK 1,8I/B4184S11 5VXL/MTX75 5DR HGV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.105 A
5024 7450	W530080 150 SEK	Volvo V50 -06 Coil	1,8 KOMBI 125HK 1,8I/B4184S11 5VXL/MTX75 5DR HGV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.105 A