

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4949 7440	W735836 500 SEK	VW Golf, e-Golf -19 Steering wheel lock / Ignition lock	1.6 TDI DIESEL VARIANT 116HK 1.6/DGTE AUTOMAT 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.839 A
4949 7440	W732335 500 SEK	VW Golf, e-Golf -18 Steering wheel lock / Ignition lock	2.0 GTD 4-M CROSSOVER 184HK 2.0/DGCA AUTOMAT 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	5.915 A
4949 7440	W731399 500 SEK	VW Golf, e-Golf -19 Steering wheel lock / Ignition lock	1.5 TGI VARIANT BIOGAS 131HK 1.5/TGIDHFA 6VXLSEL 5 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.960 A
4949 7440	W729337 500 SEK	VW Golf, e-Golf -17 Steering wheel lock / Ignition lock	1.4 TSI VARIANT 150HK 1.4/TSICZDA AUTOMAT 5DR HGV B TESTAD OK	Vimmerby Bildemontering AB 0492-20028	17.873 A
4949 7440	W715760 500 SEK	VW Golf, e-Golf -19 Steering wheel lock / Ignition lock	1.6 TDI DIESEL KOMBISEDAN 116HK 1.6/TDIDGTE 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.994 A
4949 7440	W707226 500 SEK	VW Golf, e-Golf -18 Steering wheel lock / Ignition lock	2.0 TDI 4-MOTION VARIANT 150HK 2.0/TDIDCYA 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.288 A
4949 7440	W707128 500 SEK	VW Golf, e-Golf -18 Steering wheel lock / Ignition lock	1.4 TSI MULTIFUEL VARIANT 125HK 1.4/CPVB 6VXL 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.493 A
4949 7440	W703503 500 SEK	VW Golf, e-Golf -15 Steering wheel lock / Ignition lock	1.4 TGI BIFUEL VARIANT 110HK 1.4/CPWA AUTOMAT 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	16.011 A
4949 7440	W703211 500 SEK	VW Golf, e-Golf -18 Steering wheel lock / Ignition lock	1.4 TGI BIFUEL KOMBISEDAN 110HK 1.4/CPWA 6VXL 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.549 A
4949 7440	W702674 500 SEK	VW Golf, e-Golf -15 Steering wheel lock / Ignition lock	1.6 TDI KOMBISEDAN 105HK 1.6/CLHA AUTOMAT 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	21.245 A
4949 7440	W697081 500 SEK	VW Golf, e-Golf -16 Steering wheel lock / Ignition lock	1.6 TDI DIESEL VARIANT 110HK 1.6/TDIDBKA 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	28.531 A
4949 7440	W693776 500 SEK	VW Golf, e-Golf -18 Steering wheel lock / Ignition lock	1.4 TSI MULTIFUEL KOM-SEDAN 125HK 1.4/TSICPVB 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	2.132 A
4949 7440	W692811 500 SEK	VW Golf, e-Golf -16 Steering wheel lock / Ignition lock	1.6 TDI DIESEL VARIANT 110HK 1.6/TDIDBKA 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.932 A
4949 7440	W686423 500 SEK	VW Golf, e-Golf -14 Steering wheel lock / Ignition lock	1.6 TDI DIESEL KOMBISEDAN 105HK 1.6/TDIDCLHA AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.009 A
4949 7440	W686008 500 SEK	VW Golf, e-Golf -14 Steering wheel lock / Ignition lock	1.4 TSI MULTIFUEL 122HK 1.4/TSICPVA 6VXL 5DR CSE ETA TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.000 A
4949 7440	W672218 500 SEK	VW Golf, e-Golf -17 Steering wheel lock / Ignition lock	1.2 TSI VARIANT 110HK 1.2/TSICYVB 6VXL 5DR HGV BENS TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.498 A
4949 7440	W665615 500 SEK	VW Golf, e-Golf -16 Steering wheel lock / Ignition lock	2.0 GTD 4-MOTION CROSSOVER 184HK 2.0/GTDICUNA AUTOMAT TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	13.402 A
4949 7440	W602509 500 SEK	VW Golf, e-Golf -16 Steering wheel lock / Ignition lock	1.4 TSI KOMBISEDAN 150HK GAS 1.4/TSICPWA AUTOMAT 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.980 A
4949 7440	W601527 500 SEK	VW Golf, e-Golf -14 Steering wheel lock / Ignition lock	1.6 TDI CC 110HK 1.6/TDIDCRKB 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	11.139 A
4949 7440	W594451 500 SEK	VW Golf, e-Golf -17 Steering wheel lock / Ignition lock	1.4 TSI VARIANT 150HK 1.4/TSICZDA AUTOMAT 5DR CBI BE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.100 A
4949 7440	W581520 500 SEK	VW Golf, e-Golf -17 Steering wheel lock / Ignition lock	1.4 TSI KOMBISEDAN 125HK 1.4/TSICPVB 6VXL 5DR CC ET TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.866 A
4949 7440	W577949 500 SEK	VW Golf, e-Golf -15 Steering wheel lock / Ignition lock	1.4 TSI 125HK 1.4/TSICPVB 6VXL/PRL 5DR HGV ETANOL E8 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	11.204 A
4949 7440	W572948 500 SEK	VW Golf, e-Golf -14 Steering wheel lock / Ignition lock	1.6 TDI 4-MOTION KOMBISEDAN 105HK 1.6/TDIDCLHA 6VXL/MRV 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.675 A
4949 7440	W568801 500 SEK	VW Golf, e-Golf -15 Steering wheel lock / Ignition lock	1.2 TSI KOMBISEDAN 105HK 1.2/TSICJZA 6VXL/PRL 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.138 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4949 7440	W717854 500 SEK	VW Golf, e-Golf -14 Steering wheel lock / Ignition lock	1.4 TSI MULTIFUEL KOMBISE122HK 1.4TSI/CPVA 5VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A
4949 7440	W672970	VW Golf, e-Golf -18 Steering wheel lock / Ignition lock	2.0TDI 4-MOTION DIESEL 150HK 2.0TDI/DCYA 6VXL 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.692 A
4949 7440	W692328	VW Golf, e-Golf -15 Steering wheel lock / Ignition lock	1.6 TDI DIESEL VARIANT 110HK 1.6TDI/CRKB 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A