

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3528 3008	W544373 200 SEK	Opel Astra -15 Handle exterior Right	1.6CDTI DIESEL KOMBI 110HK 1.6CDTI/B16DTL 6VXL 5DR H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	7.443 A
3528 3008	W544374 200 SEK	Opel Astra -15 Handle exterior Right	1.6CDTI DIESEL KOMBI 110HK 1.6CDTI/B16DTL 6VXL 5DR H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	7.443 A
3528 3008	W532731 200 SEK	Opel Astra -10 Handle exterior Right	1.7CDTI DIESEL 125HK 1.7CDTI/A17DTR 6VXL/MZ4 5DR CC H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	17.164 A
3528 3008	W515697 200 SEK	Opel Astra -10 Handle exterior Right	1.6-16V 116HK 1.6/A16XER MANUELL 5DR CSE BENSIN H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	14.310 A
3528 3008	W515696 200 SEK	Opel Astra -10 Handle exterior Right	1.6-16V 116HK 1.6/A16XER MANUELL 5DR CSE BENSIN H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	14.310 A
3528 3008	W725245 200 SEK	Opel Astra -12 Handle exterior Right	1.7 CDTI KOMBI-SEDAN 131HK 1.7CDTI/A17DTS 5DR CSE D H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	18.653 A
3528 3008	W725246 200 SEK	Opel Astra -12 Handle exterior Right	1.7 CDTI KOMBI-SEDAN 131HK 1.7CDTI/A17DTS 5DR CSE D H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	18.653 A
3528 3008	W684194 200 SEK	Opel Astra -13 Handle exterior Right	1.7 CDTI DIESEL KOMBI 110HK 1.7 CDTI/A17DTE 5DR HGV H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	18.108 A
3528 3008	W684193 200 SEK	Opel Astra -13 Handle exterior Right	1.7 CDTI DIESEL KOMBI 110HK 1.7 CDTI/A17DTE 5DR HGV H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	18.108 A
3528 3008	W683465 200 SEK	Opel Astra -12 Handle exterior Right	1.7 CDTI DIESEL KOMBI 110HK 1.7/A17DTC 6VXL 5DR HGV H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	24.086 A
3528 3008	W683464 200 SEK	Opel Astra -12 Handle exterior Right	1.7 CDTI DIESEL KOMBI 110HK 1.7/A17DTC 6VXL 5DR HGV H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	24.086 A
3528 3008	W650281 200 SEK	Opel Astra -15 Handle exterior Right	1.6CDTI DIESEL KOMBI 110HK 1.6CDTI/B16DTL 6VXL 5DR H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	5.924 A
3528 3008	W650282 200 SEK	Opel Astra -15 Handle exterior Right	1.6CDTI DIESEL KOMBI 110HK 1.6CDTI/B16DTL 6VXL 5DR H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	5.924 A
3528 3008	W641329 200 SEK	Opel Astra -11 Handle exterior Right	1.3CDTI DIESEL CC 95HK 1.3CDTI/A13DTE 6VXL 5DR CC D H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	15.340 A
3528 3008	W633708 200 SEK	Opel Astra -11 Handle exterior Right	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	16.987 A
3528 3008	W633707 200 SEK	Opel Astra -11 Handle exterior Right	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	16.987 A
3528 3008	W603671 200 SEK	Opel Astra -11 Handle exterior Right	1.7CDTI KOMBI-SEDAN 125HK 1.7CDTI/A17DTR 6VXL 5DR C H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	15.092 A
3528 3008	W603670 200 SEK	Opel Astra -11 Handle exterior Right	1.7CDTI KOMBI-SEDAN 125HK 1.7CDTI/A17DTR 6VXL 5DR C H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	15.092 A
3528 3008	W597789 200 SEK	Opel Astra -15 Handle exterior Right	1.4I TURBO KOMBI 140HK 1.4I/B14NET MZ4 5DR HGV BENS H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	6.624 A
3528 3008	W597788 200 SEK	Opel Astra -15 Handle exterior Right	1.4I TURBO KOMBI 140HK 1.4I/B14NET MZ4 5DR HGV BENS H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	6.624 A
3528 3008	W570888 200 SEK	Opel Astra -11 Handle exterior Right	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR H.FRAM TESTAD OK H.FRAM	Vimmerby Bildemontering AB 0492-20028	13.310 A
3528 3008	W570886 200 SEK	Opel Astra -11 Handle exterior Right	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR H.BAK TESTAD OK H.BAK	Vimmerby Bildemontering AB 0492-20028	13.310 A
3528 3008	W532732 200 SEK	Opel Astra -10 Handle exterior Right	1.7CDTI DIESEL 125HK 1.7CDTI/A17DTR 6VXL/MZ4 5DR CC H.FRAM 2ST SKAV, SE BILD H.FRAM	Vimmerby Bildemontering AB 0492-20028	17.164 A*
3528 3008	W641328 200 SEK	Opel Astra -11 Handle exterior Right	1.3CDTI DIESEL CC 95HK 1.3CDTI/A13DTE 6VXL 5DR CC D H.BAK LACKSLÄPP, SE BILD H.BAK	Vimmerby Bildemontering AB 0492-20028	15.340 A*