

| VCode<br>PCode | Stock no.<br>Price | Vehicle<br>Part             | Vehicle Information<br>Part Information                         | Company<br>Phone                         | Milage<br>Quality |
|----------------|--------------------|-----------------------------|---|--|-------------------|
| 3528<br>7140   | W649282            | Opel Astra -15<br>Rear axle | 1.6CDTI DIESEL KOMBI 110HK 1.6CDTI/B16DTL 6VXL 5DR<br>TESTAD OK | Vimmerby Bildemontering AB<br>0492-20028 | 5.924<br>A        |
| 3528<br>7140   | W570681            | Opel Astra -11<br>Rear axle | 1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR              | Vimmerby Bildemontering AB<br>0492-20028 | 13.310<br>A       |