

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
1520 7498	W675931 500 SEK	BMW 1-Series -08 Other Control unit	118 2.0D (E81, E87) 143HK 2.0D/N47-D20A AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.722 A
1520 7498	W675933 375 SEK	BMW 1-Series -08 Other Control unit	118 2.0D (E81, E87) 143HK 2.0D/N47-D20A AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.722 A
1520 7498	W675961 300 SEK	BMW 1-Series -08 Other Control unit	118 2.0D (E81, E87) 143HK 2.0D/N47-D20A AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.722 A
1520 7498	W673973 1.000 SEK	BMW 1-Series -11 Other Control unit	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.717 A
1520 7498	W651882 300 SEK	BMW 1-Series -07 Other Control unit	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7498	W651866 2.000 SEK	BMW 1-Series -07 Other Control unit	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7498	W645576 300 SEK	BMW 1-Series -08 Other Control unit	2.0D CC 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.860 A
1520 7498	W636720 1.000 SEK	BMW 1-Series -11 Other Control unit	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7498	W635224 1.000 SEK	BMW 1-Series -09 Other Control unit	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7498	W613356 2.000 SEK	BMW 1-Series -09 Other Control unit	118D 2.0D DIESEL CC 143HK 2.0D/N47D20C 6VXL 3DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.743 A
1520 7498	W540328 300 SEK	BMW 1-Series -07 Other Control unit	120 2.0D DIESEL 177HK 2.0D/N47D20A AUT/GA6HP19Z 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.415 A
1520 7498	W540341 2.000 SEK	BMW 1-Series -07 Other Control unit	120 2.0D DIESEL 177HK 2.0D/N47D20A AUT/GA6HP19Z 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.415 A
1520 7498	W527264 1.500 SEK	BMW 1-Series -09 Other Control unit	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7498	W442458 400 SEK	BMW 1-Series -08 Other Control unit	118D 2.0D 143HK 2.0D/N47-D20A 6VXL 5DR CC DIESEL TESTAD, OK! (H.FRAME)	Vimmerby Bildemontering AB 0492-20028	9.882 A
1520 7498	W441772 2.000 SEK	BMW 1-Series -07 Other Control unit	120D 2.0D 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.048 A
1520 7498	W397486 400 SEK	BMW 1-Series -07 Other Control unit	120 2.0D 163HK 5DR CC-KAROSS 2.0D/N47TJ2D20 AUTOMAT TESTAD, OK! H.FRAME	Vimmerby Bildemontering AB 0492-20028	17.827 A
1520 7498	W293044 300 SEK	BMW 1-Series -08 Other Control unit	2.0D CC-KAROSS 177HK 2.0D/N47-D20A 6VXL 5DR CC DIES TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.664 A
1520 7498	W675835	BMW 1-Series -08 Other Control unit	2.0D 118D KOMBI-SEDAN 143HK 2.0D/N47D20A 6VXL 3DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.151 A
1520 7498	W674172	BMW 1-Series -07 Other Control unit	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7498	W674177	BMW 1-Series -07 Other Control unit	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7498	W674174	BMW 1-Series -07 Other Control unit	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7498	W674175	BMW 1-Series -07 Other Control unit	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7498	W674000	BMW 1-Series -11 Other Control unit	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.717 A
1520 7498	W673967	BMW 1-Series -11 Other Control unit	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.717 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
1520 7498	W673970	BMW 1-Series -11 Other Control unit	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.717 A
1520 7498	W673952	BMW 1-Series -11 Other Control unit	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.717 A
1520 7498	W651865	BMW 1-Series -07 Other Control unit	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7498	W651867	BMW 1-Series -07 Other Control unit	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7498	W651839	BMW 1-Series -07 Other Control unit	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7498	W645552	BMW 1-Series -08 Other Control unit	2.0D CC 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.860 A
1520 7498	W645580	BMW 1-Series -08 Other Control unit	2.0D CC 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.860 A
1520 7498	W645553	BMW 1-Series -08 Other Control unit	2.0D CC 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.860 A
1520 7498	W645540	BMW 1-Series -08 Other Control unit	2.0D CC 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.860 A
1520 7498	W636704	BMW 1-Series -11 Other Control unit	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7498	W636706	BMW 1-Series -11 Other Control unit	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7498	W636716	BMW 1-Series -11 Other Control unit	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7498	W635145	BMW 1-Series -09 Other Control unit	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7498	W635225	BMW 1-Series -09 Other Control unit	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7498	W635231	BMW 1-Series -09 Other Control unit	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7498	W635223	BMW 1-Series -09 Other Control unit	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7498	W635219	BMW 1-Series -09 Other Control unit	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7498	W613996	BMW 1-Series -07 Other Control unit	120 2.0D DIESEL CC 163HK 2.0D/N47TU2D20 6VXL 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	17.600 A
1520 7498	W565015	BMW 1-Series -09 Other Control unit	118 2.0D 143HK 2.0D/N47D20C 6VXL/GS617DG 5DR CC DIE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.089 A
1520 7498	W564950	BMW 1-Series -09 Other Control unit	118 2.0D 143HK 2.0D/N47D20C 6VXL/GS617DG 5DR CC DIE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.089 A
1520 7498	W564931	BMW 1-Series -09 Other Control unit	118 2.0D 143HK 2.0D/N47D20C 6VXL/GS617DG 5DR CC DIE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.089 A
1520 7498	W546838	BMW 1-Series -11 Other Control unit	116 2.0D KOMBI-SEDAN 116HK 2.0D/N47D20C 6VXL/GS617D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.313 A
1520 7498	W546847	BMW 1-Series -11 Other Control unit	116 2.0D KOMBI-SEDAN 116HK 2.0D/N47D20C 6VXL/GS617D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.313 A
1520 7498	W546829	BMW 1-Series -11 Other Control unit	116 2.0D KOMBI-SEDAN 116HK 2.0D/N47D20C 6VXL/GS617D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.313 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
1520 7498	W544621	BMW 1-Series -10 Other Control unit	118D 2.0D DIESEL 143HK 2.0D/N47D20C 6VXL/GS617DG 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.141 A
1520 7498	W544629	BMW 1-Series -10 Other Control unit	118D 2.0D DIESEL 143HK 2.0D/N47D20C 6VXL/GS617DG 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.141 A
1520 7498	W544615	BMW 1-Series -10 Other Control unit	118D 2.0D DIESEL 143HK 2.0D/N47D20C 6VXL/GS617DG 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.141 A
1520 7498	W540329	BMW 1-Series -07 Other Control unit	120 2.0D DIESEL 177HK 2.0D/N47D20A AUT/GA6HP19Z 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.415 A
1520 7498	W540342	BMW 1-Series -07 Other Control unit	120 2.0D DIESEL 177HK 2.0D/N47D20A AUT/GA6HP19Z 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.415 A
1520 7498	W540388	BMW 1-Series -07 Other Control unit	120 2.0D DIESEL 177HK 2.0D/N47D20A AUT/GA6HP19Z 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.415 A
1520 7498	W527265	BMW 1-Series -09 Other Control unit	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7498	W527263	BMW 1-Series -09 Other Control unit	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7498	W527325	BMW 1-Series -09 Other Control unit	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7498	W527323	BMW 1-Series -09 Other Control unit	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7498	W527262	BMW 1-Series -09 Other Control unit	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7498	W442403	BMW 1-Series -08 Other Control unit	118D 2.0D 143HK 2.0D/N47-D20A 6VXL 5DR CC DIESEL TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.882 A