

Stock no.:

W109376

105 SEK

Shipping price / Shipping time:

- / 1-3 days

Svensk Bilåtervinning AB

Industrivägen 8

71531 Odensbacken

Tel.: 019-450690

Fax: 019-450692

www.svenskbilatervinning.se



Part - Washer pump rear hatch

Stock no.:	Position:	Quality:	Fits fr./to m.y
W109376		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
	DENSO	060210-1480 DENSO	-
Description:	TESTAD OK, 2 STIFT		

Vehicle - Suzuki Grand Vitara

Chassi no.:	Model year:	Milage:	Fuel:
JSAHTX92V00206134	2004	13.068	Bensin
Colour:	Colour code:	Interior:	Interior code:
SILVERMET	Z25	L-GRÅTT SKINN	C03
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
AUT (04FT112226)	AISIN A46092142	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
2,7I V6 (135KW)	H27A (KOMP: 11,5-12 BAR) -		20041209
Description:	5DSUV XL7 2,7I V6 AUT 4WDABS,ACC,DRAG,SERVO,C-LÅS		



Direct link: <http://www.bildelsbasen.se/170-W109376.html>