

Stock no.:

W553730

300 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Kylfläktsmotstånd

Stock no.:	Position:	Quality:	Fits fr./to m.y
W553730		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad OK			

Vehicle - Subaru Justy

Chassi no.:	Model year:	Milage:	Fuel:
JDAM300F001003374	2008	-	Bensin
Colour:	Colour code:	Interior:	Interior code:
LGRÅ	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
5vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.0i/1KRFE	-	200708	2008-06-18
Description:			
1.0I 69HK 1.0I/1KRFE 5VXL 5DR CC BENSIN			

Direct link: <http://www.bildelsbasen.se/141-W553730.html>