

Stock no.:

**W559999**

# Pris saknas

Shipping price / Shipping time:

- / 1-3 days

## Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

[www.vimmerbybildemontering.se](http://www.vimmerbybildemontering.se)



### Part - Handle exterior

Stock no.:	Position:	Quality:	Fits fr./to m.y
W559999	Left	A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
v.skjutdörr Testad OK v.skjutdörr			

### Vehicle - Opel Vivaro

Chassi no.:	Model year:	Milage:	Fuel:
WOLF7BHBH8V645834	2008	14.364	Diesel
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
AUTOMAT	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
2.0CDTi/M9R781	93169303	-	2008-04-01
Description:			
2.0CDTI DIESEL SKÅP 114HK 2.0CDTI/M9R781 AUTOMAT 0D			

Direct link: <http://www.bildelsbasen.se/141-W559999.html>