

Stock no.:

**W599842**

# Pris saknas

Shipping price / Shipping time:

- / 1-3 days

## Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

[www.vimmerbybildemontering.se](http://www.vimmerbybildemontering.se)



### Part - Hub rear

Stock no.:	Position:	Quality:	Fits fr./to m.y
W599842	Rear	A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad OK			

### Vehicle - Citroen C1

Chassi no.:	Model year:	Milage:	Fuel:
VF7PNCFAC89425223	2010	-	Bensin
Colour:	Colour code:	Interior:	Interior code:
SILVER	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
AUTOMAT	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.0i/CFA	-	201002	2010-02-15
Description:			
1.0I KOMBI-SEDAN 68HK 1.0I/CFA AUTOMAT 5DR CC BENSI			

Direct link: <http://www.bildelsbasen.se/141-W599842.html>