

Stock no.:

W608201

2.000 SEK

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Drive shaft

Stock no.:	Position:	Quality:	Fits fr./to m.y
W608201	Right front	A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad Ok			

Vehicle - Mazda 3

Chassi no.:	Model year:	Milage:	Fuel:
JMZBK14F691825776	2009	21.323	Bensin
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
6vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
2.0i/LF	-	200811	2009-02-10
Description:			
2.0I CC 150HK 2.0I/LF 6VXL 5DR CC BENSIN			

Direct link: <http://www.bildelsbasen.se/141-W608201.html>