

Stock no.:

W614497

Pris saknas

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källenas 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Kamera Utvändig

Stock no.:	Position:	Quality:	Fits fr./to m.y
W614497		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad OK			

Vehicle - Opel Movano

Chassi no.:	Model year:	Milage:	Fuel:
W0LVSU4V2EB053995	2014	27.800	Diesel
Colour:	Colour code:	Interior:	Interior code:
VIT	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
6vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
2.3CDTi/M9T880	-	-	2014-04-17
Description:			
2.3CDTI DIESEL FLAK 150HK 2.3CDTI/M9T880 6VXL ODR F			

Direct link: <http://www.bildelsbasen.se/141-W614497.html>