

Stock no.:

W635686

Pris saknas

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Rear sensor

Stock no.:	Position:	Quality:	Fits fr./to m.y
W635686		A	-
New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-
Description:			
Testad OK			

Vehicle - Volvo C30

Chassi no.:	Model year:	Milage:	Fuel:
YV1MK84E1B2222551	2011	15.170	Diesel
Colour:	Colour code:	Interior:	Interior code:
RÖD	-	-	-
Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
6vxl	-	-	-
Engine:	Engine code:	Manufacturing date:	Registration date:
1.6D/D4162T	-	201006	2010-06-22
Description:			
1.6D D2 SPORTCOUPE 114HK 1.6D/D4162T 6VXL 3DR CC DI			



Direct link: <http://www.bildelsbasen.se/141-W635686.html>