

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4928 4642	W29399 150 SEK	VW Passat -05 Rubber strip rear window Rear	VW PASSAT 2,0 FSI	Köpings Bildemontering AB 0221-17933	26.587 A
4032 4642	W29024 200 SEK	Saab 900 -88 Rubber strip rear window	2.0 I JUB-KAT MAN VB FÖNSTER	Eskilstuna Bildemontering AB 016-139906	15.334 A
1732 4642	W7910 200 SEK	Citroen C4 -14 Rubber strip rear window Inner Rear	CITROEN N OK , DV6C	Malmby Bilskrot AB 073-7513592	9.490 A
5206 4642	W39738 250 SEK	Hyundai Santa Fe -06 Rubber strip rear window	HYUNDAI SANTA FE I 2.4	H&K Bildemontering AB 0141-219822	15.556 A
4036 4642	W325769 270 SEK	Saab 9-3 -06 Rubber strip rear window	9-3 URKODAD 1,9TID 5VXL 5DR CBI DIESEL I PLAST VF VÄNSTER FRAM	Boets Bildemontering AB 0144-20040	- A
5078 4642	W31156 280 SEK	Volvo V60 -16 Rubber strip rear window Rear	VOLVO BAKLUCKA	Köpings Bildemontering AB 0221-17933	9.939 A
1501 4642	W9338 300 SEK	BMW Z3 -99 Rubber strip rear window	BMW Z3 ROADSTER 193HK 2.8i BENS MENUELL	Strängnäs Bilskrot AB 0152-25500	13.184 A
5578 4642	W14889 300 SEK	KIA Picanto -13 Rubber strip rear window Rear	KIA PICANTO 1,0 ECO 5D, GUMMLIST FÖR BAKLUCKA , G3LA	Malmby Bilskrot AB 073-7513592	6.480 A
4209 4642	W9708 300 SEK	Skoda Octavia -14 Rubber strip rear window Rear	SKODA 5E OK , CPWA	Malmby Bilskrot AB 073-7513592	45.319 A
1575 4642	W976032 300 SEK	BMW i3-Series -16 Rubber strip rear window Rear	01 13 REX 1B1P25B AUTO 3DR KOMBI-SEDAN ELHYBRID BE	Upplands Bildemontering AB 018-169225	1.077 A
2983 4642	W1118159 305 SEK	Jaguar XJS -95 Rubber strip rear window Rear	JAGUAR XJS 9EPONA AUTOMAT 2DR CABRIOLET BENSIN	Karstors Bildemontering AB 011-4954000	16.458 A
3952 4642	W257383 320 SEK	LandRover Freelander -00 Rubber strip rear window	FREELANDER 1,8i-16V 5VXL AWD 3DR SUV BENSIN SKRAPLIST	Boets Bildemontering AB 0144-20040	- A
7737 4642	W17234 350 SEK	Peugeot 404 -72 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	- A
4209 4642	W9547 350 SEK	Skoda Octavia -14 Rubber strip rear window Rear	SKODA 5E OK , CPWA	Malmby Bilskrot AB 073-7513592	45.319 A
1539 4642	W253370 370 SEK	BMW 5-Series -07 Rubber strip rear window	523i TOURING 2,5i-24V AUT 5DR CBI BENSIN	Boets Bildemontering AB 0144-20040	16.014 A
2791 4642	W28507 375 SEK	Honda CR-V -13 Rubber strip rear window Rear	HONDA	Köpings Bildemontering AB 0221-17933	49.472 A
1746 4642	W1553100 375 SEK	Citroen C4 Cactus -18 Rubber strip rear window	CITROEN C4 CACTUS 1,2 HNZ TRONIC 5DR MPV BENSIN VB	Ådalens Bildemontering AB 0612-12420	189 A
4589 4642	W363963 395 SEK	Toyota Hilux -98 Rubber strip rear window	4WD 2,4 TD 5VXL 4WD 4DR PIC DIESEL	Begagnade Bil delar i Linköping AB / Norrköping 013-100110	23.859 A
3298 4642	W1309658 400 SEK	Mercedes A-Class -20 Rubber strip rear window Rear	2,0 T. MERCEDES AMG A35 4MATIC 260920 - 30154659 7 BAK	Örebro Bildemontering AB 019-6701200	1.164 A
4422 4642	W4987 400 SEK	Suzuki Swift -11 Rubber strip rear window Rear	SUZUKI SWIFT OK , K12B	Malmby Bilskrot AB 073-7513592	9.616 A
4527 4642	W322803 470 SEK	Toyota Yaris -07 Rubber strip rear window	YARIS 1,4D-4D 5VXL 4DR CSE DIESEL LITE GRÖNTONAD	Boets Bildemontering AB 0144-20040	14.521 A
4975 4642	W26363 495 SEK	VW Caddy -03 Rubber strip rear window	VW CADDY SKÅP 1,9 TDI ALH M 3DR DIESEL GUMMLIST HÖGER BAKDÖRR HB	Fornåsa Bildemontering AB 013-103103	- A
4975 4642	W26362 618 SEK	VW Caddy -03 Rubber strip rear window	VW CADDY SKÅP 1,9 TDI ALH M 3DR DIESEL GUMMLIST VÄNSTER BAKDÖRR VB	Fornåsa Bildemontering AB 013-103103	- A
5384 4642	W587829 625 SEK	Microcar M.Go -17 Rubber strip rear window Rear	DUE AUTOMAT	Atracco AB - Linköping 013-397024	1.278 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5350 4642	W940686 706 SEK	Cupra Ateca -20 Rubber strip rear window Rear	CUPRA ATECA 19- DNUE 4 CYL INSP 2,0 AUTOMAT/DSG 5D PR-4ZD, SVART DEKORLIST	Karstorps Bildemontering AB 011-4954000	691 A
4961 4642	W1020625 744 SEK	VW ID.4 -21 Rubber strip rear window Rear	VW ID4 EBJA AUTOMAT 5DR KOMBI EL	Karstorps Bildemontering AB 011-4954000	2.483 A
4961 4642	W1015869 744 SEK	VW ID.4 -22 Rubber strip rear window Rear	VW ID 4 21- BL1G AUTOMAT 5DR KOMBI EL	Karstorps Bildemontering AB 011-4954000	612 A
5466 4642	W123300	Lexus IS -15 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	9.523 A
2494 4642	W120433	Ford Transit -08 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	26.812 A
5570 4642	W119604	KIA Sorento -06 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	26.200 A