

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4961 4642	W1015869 744 SEK	VW ID.4 -22 Rubber strip rear window Rear	VW ID 4 21- BL1G AUTOMAT 5DR KOMBI EL	Karstors Bildemontering AB 011-4954000	612 A
4961 4642	W1020625 744 SEK	VW ID.4 -21 Rubber strip rear window Rear	VW ID4 EBJA AUTOMAT 5DR KOMBI EL	Karstors Bildemontering AB 011-4954000	2.483 A
3298 4642	W1309658 400 SEK	Mercedes A-Class -20 Rubber strip rear window Rear	2,0 T. MERCEDES AMG A35 4MATIC 260920 - 30154659 7 BAK	Örebro Bildemontering AB 019-6701200	1.164 A
5350 4642	W940686 706 SEK	Cupra Ateca -20 Rubber strip rear window Rear	CUPRA ATECA 19- DNUE 4 CYL INSP 2,0 AUTOMAT/DSG 5D PR-4ZD, SVART DEKORLIST	Karstors Bildemontering AB 011-4954000	691 A
1798 4642	W435546	DS 7 Crossback -19 Rubber strip rear window	DS7 CROSSBACK 1.6 PURETECH AUT SUV BENSIN VB VÄNSTER BAK	Boets Bildemontering AB 0144-20040	4.121 A
1746 4642	W1553100 375 SEK	Citroen C4 Cactus -18 Rubber strip rear window	CITROEN C4 CACTUS 1,2 HNZ TRONIC 5DR MPV BENSIN VB	Ådalens Bildemontering AB 0612-12420	189 A
5384 4642	W587829 625 SEK	Microcar M.Go -17 Rubber strip rear window Rear	DUE AUTOMAT	Atracco AB - Linköping 013-397024	1.278 A
5078 4642	W31156 280 SEK	Volvo V60 -16 Rubber strip rear window Rear	VOLVO BAKLUCKA	Köpings Bildemontering AB 0221-17933	9.939 A
1575 4642	W976032 300 SEK	BMW i3-Series -16 Rubber strip rear window Rear	01 13 REX IB1P25B AUTO 3DR KOMBI-SEDAN ELHYBRID BE	Upplands Bildemontering AB 018-169225	1.077 A
5466 4642	W123300	Lexus IS -15 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	9.523 A
3127 4642	W2363977	Lancia Voyager -14 Rubber strip rear window Rear	LANCIA RT VOYAGER G AUTOMAT 5DR MPV BENSIN	Atracco AB - Hedemora 0225-595540	6.464 A
4209 4642	W9708 300 SEK	Skoda Octavia -14 Rubber strip rear window Rear	SKODA 5E OK , CPWA	Malmby Bilskrot AB 073-7513592	45.319 A
4209 4642	W9547 350 SEK	Skoda Octavia -14 Rubber strip rear window Rear	SKODA 5E OK , CPWA	Malmby Bilskrot AB 073-7513592	45.319 A
1732 4642	W7910 200 SEK	Citroen C4 -14 Rubber strip rear window Inner Rear	CITROEN N OK , DV6C	Malmby Bilskrot AB 073-7513592	9.490 A
2791 4642	W28507 375 SEK	Honda CR-V -13 Rubber strip rear window Rear	HONDA	Köpings Bildemontering AB 0221-17933	49.472 A
5578 4642	W14889 300 SEK	KIA Picanto -13 Rubber strip rear window Rear	KIA PICANTO 1,0 ECO 5D, GUMMLIST FÖR BAKLUCKA , G3LA	Malmby Bilskrot AB 073-7513592	6.480 A
4422 4642	W4987 400 SEK	Suzuki Swift -11 Rubber strip rear window Rear	SUZUKI SWIFT OK , K12B	Malmby Bilskrot AB 073-7513592	9.616 A
2494 4642	W120433	Ford Transit -08 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	26.812 A
4928 4642	W104498	VW Passat -08 Rubber strip rear window	VW PASSAT VAR GT SPORT BMR A 5DR DIESEL	Nya Högåsens Bildemontering AB 070-1725219	23.366 A
3592 4642	W97762	Opel Vivaro -08 Rubber strip rear window	OPEL VIVARO SKÅP M9R-780 2.0 CDTI ODR DIESEL	Nya Högåsens Bildemontering AB 070-1725219	25.987 A
4928 4642	W108949	VW Passat -07 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	23.442 A
4527 4642	W322803 470 SEK	Toyota Yaris -07 Rubber strip rear window	YARIS 1,4D-4D 5VXL 4DR CSE DIESEL LITE GRÖNTONAD	Boets Bildemontering AB 0144-20040	14.521 A
1539 4642	W253370 370 SEK	BMW 5-Series -07 Rubber strip rear window	523I TOURING 2,5i-24V AUT 5DR CBI BENSIN	Boets Bildemontering AB 0144-20040	16.014 A
5570 4642	W119604	KIA Sorento -06 Rubber strip rear window		AAA Bildemontering i Skutskär AB 026-79100	26.200 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5206 4642	W39738 250 SEK	Hyundai Santa Fe -06 Rubber strip rear window	HYUNDAI SANTA FE I 2.4	H&K Bildemontering AB 0141-219822	15.556 A
4036 4642	W325769 270 SEK	Saab 9-3 -06 Rubber strip rear window	9-3 URKODAD 1,9TID 5VXL 5DR CBI DIESEL I PLAST VF VÄNSTER FRAM	Boets Bildemontering AB 0144-20040	- A
4477 4642	W114360	Suzuki Grand Vitara -05 Rubber strip rear window	J20A , 2.0 4WD 140 HK RIGHT	AAA Bildemontering i Skutskär AB 026-79100	- A
4477 4642	W114359	Suzuki Grand Vitara -05 Rubber strip rear window	J20A , 2.0 4WD 140 HK LEFT	AAA Bildemontering i Skutskär AB 026-79100	- A
4928 4642	W29399 150 SEK	VW Passat -05 Rubber strip rear window Rear	VW PASSAT 2,0 FSI	Köpings Bildemontering AB 0221-17933	26.587 A
4913 4642	W448754	VW Golf, e-Golf -04 Rubber strip rear window	GOLF VAR 1,6 1,6 AUT 5DR CBI BENSIN HB HÖGER BAK MED LITEN RUTA	Boets Bildemontering AB 0144-20040	- A