

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|---------------------|------------------------------------|---|--|-------------------|
| 5063 7819 | W2104815 375 SEK | Volvo V70 -10 Bonnet isolation | V70 D5244T14 AUT TF-80SC FWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 26.364 A |
| 5063 7819 | W2103945 375 SEK | Volvo V70 -10 Bonnet isolation | V70 D4164T MAN MTX75 FWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 32.811 A |
| 5064 7819 | W2102594 375 SEK | Volvo V70 -14 Bonnet isolation | V70 D5204T3 MAN M66 FWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 30.372 A |
| 5064 7819 | W2100188 375 SEK | Volvo V70 -14 Bonnet isolation | V70 D5204T3 MAN M66 FWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 21.313 A |
| 5063 7819 | W2089088 375 SEK | Volvo V70 -13 Bonnet isolation | V70 D5244T11 MAN M66 FWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 8.306 A |
| 5083 7819 | W2082732 375 SEK | Volvo XC70 -11 Bonnet isolation | XC70 D5244T16 MAN M66 AWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 30.716 A |
| 5064 7819 | W2073928 375 SEK | Volvo V70 -15 Bonnet isolation | V70 D4162T MAN MMT6 FWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 24.794 A |
| 5059 7819 | W2059130 375 SEK | Volvo S80 -07 Bonnet isolation | 1 S80 B6324S AUT TF-80SC FWD 4DR SED BENSIN | Jönköpings Bildemontering AB 010-4975900 | 30.936 A |
| 5083 7819 | W2051894 375 SEK | Volvo XC70 -13 Bonnet isolation | XC70 D5244T11 MAN M66 AWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 21.771 A |
| 5083 7819 | W2052400 375 SEK | Volvo XC70 -12 Bonnet isolation | XC70 D5244T17 AUT TF-80SC AWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 51.909 A |
| 5059 7819 | W2043432 375 SEK | Volvo S80 -09 Bonnet isolation | S80 B5254T8 AUT TF-80SC FWD 4DR SED ETANOL E85 | Jönköpings Bildemontering AB 010-4975900 | 9.698 A |
| 5063 7819 | W804616 350 SEK | Volvo V70 -11 Bonnet isolation | VOLVO V70 D3 D5204T2 AUTOMAT 5DR KOMBI DIESEL | Borås Bildemontering AB 033-230050 | 31.902 A |
| 5063 7819 | W2031897 375 SEK | Volvo V70 -10 Bonnet isolation | VOLVO B + V70 V70 D4164T MAN MTX75 FWD 5DR CBI DIES | Jönköpings Bildemontering AB 010-4975900 | 28.525 A |
| 5063 7819 | W799290 350 SEK | Volvo V70 -10 Bonnet isolation | VOLVO V70 2,4D D5244T14 AUTOMAT 5DR KOMBI DIESEL | Borås Bildemontering AB 033-230050 | 39.011 A |
| 5063 7819 | W2021399 375 SEK | Volvo V70 -09 Bonnet isolation | 1 VOLVO V70 B4204S4 MAN MTX75 FWD 5DR CBI ETANOL E8 | Jönköpings Bildemontering AB 010-4975900 | 21.061 A |
| 5063 7819 | W1996054 375 SEK | Volvo V70 -08 Bonnet isolation | 1 VOLVO V70 B4204S4 MAN MTX75 FWD 5DR CBI ETANOL E8 | Jönköpings Bildemontering AB 010-4975900 | 24.185 A |
| 5063 7819 | W790122 350 SEK | Volvo V70 -09 Bonnet isolation | VOLVO V70 2,5 FT B5254T8 MANUELL 5DR KOMBI ETANOL | Borås Bildemontering AB 033-230050 | 28.550 A |
| 5063 7819 | W232658 850 SEK | Volvo V70 -10 Bonnet isolation | 2,4TD SUNNUM 2.4TD D5244T14 6V M66 5DR CBI DIESEL | Falu Bildemontering AB 023-25530 | 16.878 A* |
| 5063 7819 | W1423689 350 SEK | Volvo V70 -11 Bonnet isolation | 01 V70 D3 2,0 6VXL 5DR HGV DIESEL | Ådalens Bildemontering AB 0612-12420 | 22.661 A* |
| 5083 7819 | W3827 800 SEK | Volvo XC70 -08 Bonnet isolation | VOLVO XC70 D5 AWD 2.4D 6-MAN 4WD CBI | Skellefteå Bildemontering AB 0910-86122 | 28.469 A |
| 5063 7819 | W80454 906 SEK | Volvo V70 -08 Bonnet isolation | 5DCBI 2,0D 6VX RÖD ABS MOMENTUM ACC ANTISPINN | Ekholms Bildemontering AB 019-577088 | 19.391 A |
| 5083 7819 | W2084454 375 SEK | Volvo XC70 -09 Bonnet isolation | XC70 D5244T4 AUT TF-80SC AWD 5DR CBI DIESEL | Jönköpings Bildemontering AB 010-4975900 | 32.942 A |
| 5059 7819 | W1215350 375 SEK | Volvo S80 -07 Bonnet isolation | S80 D5244T4 TF80SC FWD 4DR SED DIESEL | Jönköpings Bildemontering AB 010-4975900 | 27.016 A |
| 5063 7819 | W931145 375 SEK | Volvo V70 -11 Bonnet isolation | VOLVO V70 D4164T M 5DR CBI DIESEL | Norrbottnens Bildemontering AB 0929-70000 | 29.055 A* |

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|--------------------|-----------------------------------|---|---|-------------------|
| 5063 7200 | W449636 375 SEK | Volvo V70 -12 Engine casing | | AB Harrys Bilskrot 040-382200 | 13.467 A |
| 5063 7819 | W134033 | Volvo V70 -11 Bonnet isolation | | AAA Bildemontering i Skutskär AB 026-79100 | 28.618 A |