

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5060 3118	W571906 150 SEK	Volvo 940 -94 Window crank	SVART	Demia AB 0240-87850	- A
5060 3118	W571907 150 SEK	Volvo 940 -94 Window crank	SVART	Demia AB 0240-87850	- A
5051 3118	W571833 62 SEK	Volvo 740 -89 Window crank	BLÅ	Demia AB 0240-87850	- A
5051 3118	W571832 62 SEK	Volvo 740 -89 Window crank	BLÅ	Demia AB 0240-87850	- A
5060 3118	W1072637 75 SEK	Volvo 940 -91 Window crank	VOLVO 944-852 GL B230FB T 4DR SED BENSIN BLÅ, FRAM/BAK	Norrbottnens Bildemontering AB 0929-70000	30.718 A
1317 3118	W58253 175 SEK	Audi A4, S4 -99 Window crank	AUDI A4 1,8 APT M 4DR SED BENSIN	Nordiska Auto Motor AB 0700-175515	- A
1317 3118	W58254 175 SEK	Audi A4, S4 -99 Window crank	AUDI A4 1,8 APT M 4DR SED BENSIN	Nordiska Auto Motor AB 0700-175515	- A
5060 3118	W1072109 75 SEK	Volvo 940 -91 Window crank	VOLVO 944-852 GL B230FB T 4DR SED BENSIN BLÅ	Norrbottnens Bildemontering AB 0929-70000	30.718 A
1321 3118	W136026	Audi A4, S4 -07 Window crank	RIGHT	AAA Bildemontering i Skutskär AB 026-79100	17.345 A
1321 3118	W136025	Audi A4, S4 -07 Window crank	LEFT	AAA Bildemontering i Skutskär AB 026-79100	17.345 A
5575 3118	W131011	KIA Cee'd, Cee'd SW -08 Window crank	LEFT	AAA Bildemontering i Skutskär AB 026-79100	29.877 A
3837 3118	W130380	Renault Clio -08 Window crank	LEFT	AAA Bildemontering i Skutskär AB 026-79100	24.412 A
3837 3118	W130381	Renault Clio -08 Window crank	RIGHT	AAA Bildemontering i Skutskär AB 026-79100	24.412 A
5575 3118	W131012	KIA Cee'd, Cee'd SW -08 Window crank	RIGHT	AAA Bildemontering i Skutskär AB 026-79100	29.877 A
4914 3118	W57433 125 SEK	VW Golf, e-Golf -07 Window crank	VW GOLF TSI 140 BMY M 5DR CSE BENSIN	Nordiska Auto Motor AB 0700-175515	21.632 A
4914 3118	W57434 125 SEK	VW Golf, e-Golf -07 Window crank	VW GOLF TSI 140 BMY M 5DR CSE BENSIN	Nordiska Auto Motor AB 0700-175515	21.632 A
5035 3118	W134049 100 SEK	Volvo 460 -95 Window crank	VOLVO 464-313 S 2.0 B20F M 4DR BENSIN	Fyrkantens Bildemontering AB 0920-15504	- A
5035 3118	W134048 100 SEK	Volvo 460 -95 Window crank	VOLVO 464-313 S 2.0 B20F M 4DR BENSIN	Fyrkantens Bildemontering AB 0920-15504	- A
5035 3118	W134050 100 SEK	Volvo 460 -95 Window crank	VOLVO 464-313 S 2.0 B20F M 4DR BENSIN	Fyrkantens Bildemontering AB 0920-15504	- A
5035 3118	W134051 100 SEK	Volvo 460 -95 Window crank	VOLVO 464-313 S 2.0 B20F M 4DR BENSIN	Fyrkantens Bildemontering AB 0920-15504	- A
4555 3118	W7911 250 SEK	Toyota Yaris -19 Window crank Rear	TOYOTA YARIS (III) 1.5 HYBRID	Köpings Bildemontering AB 0221-17933	7.794 A
5051 3118	W568186 62 SEK	Volvo 740 -91 Window crank	VOLVO 745-886 GL B230F Z 5DR BENSIN BLÅ	Demia AB 0240-87850	- A
3308 3118	W129699	Mercedes B-Class -08 Window crank	REAR RIGHT	AAA Bildemontering i Skutskär AB 026-79100	21.390 A
3308 3118	W129698	Mercedes B-Class -08 Window crank	REAR LEFT	AAA Bildemontering i Skutskär AB 026-79100	21.390 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5060 3118	W41079 300 SEK	Volvo 940 -96 Window crank	VOLVO 945-811 S 2.3 B230FK M 5DR BENSIN	Eskilstuna Bildemontering AB 016-139906	34.613 A
3310 3118	W5212	Mercedes 200-300 (W123) 76-86 -77 Window crank	230 2,3 109HK	MERCA SKROTEN i Sverige AB 08-58358375	26.621 A
3310 3118	W5210	Mercedes 200-300 (W123) 76-86 -77 Window crank	230 2,3 109HK	MERCA SKROTEN i Sverige AB 08-58358375	26.621 A
3310 3118	W5211	Mercedes 200-300 (W123) 76-86 -77 Window crank	230 2,3 109HK	MERCA SKROTEN i Sverige AB 08-58358375	26.621 A
5050 3118	W566814 75 SEK	Volvo 740 -87 Window crank	VOLVO 744-833 B230K M 4DR BENSIN	Demia AB 0240-87850	- A
2413 3118	W63585 65 SEK	Ford Fiesta -99 Window crank	FORD FIESTA IV 1.3i LIKSIDIG	H&K Bildemontering AB 0141-219822	14.752 A