

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4953 7423	W886172 989 SEK	VW Polo -18 Window regulator	1.0 TSI CHZL 1.0 TSI CHZL MANUELL 2WD 5DR KBI BENSIN F.H	Østfold bildemontering AS (0047) -69127222	9.434 A
1439 7423	W678196 530 SEK	Dacia Sandero / Sandero Stepway -14 Window regulator	DACIA SD SANDERO H4B-400 5DR CSE BENSIN VÄNSTER BAK	Allbildelar i Huddinge AB - Västerås 010-4974230	14.441 A
4953 7423	W886123 989 SEK	VW Polo -18 Window regulator	1.0 TSI CHZL 1.0 TSI CHZL MANUELL 2WD 5DR KBI BENSIN B.V	Østfold bildemontering AS (0047) -69127222	9.434 A
1439 7423	W678197	Dacia Sandero / Sandero Stepway -14 Window regulator	DACIA SD SANDERO H4B-400 5DR CSE BENSIN HÖGER BAK	Allbildelar i Huddinge AB - Västerås 010-4974230	14.441 A
4953 7423	W886067 989 SEK	VW Polo -18 Window regulator	1.0 TSI CHZL 1.0 TSI CHZL MANUELL 2WD 5DR KBI BENSIN F.V	Østfold bildemontering AS (0047) -69127222	9.434 A
3826 7423	W678028 1.375 SEK	Renault Clio -14 Window regulator	RENAULT R CLIO K9K-608 5DR CSE DIESEL HÖGER BAK	Allbildelar i Huddinge AB - Västerås 010-4974230	20.384 A
3880 7423	W677883 2.500 SEK	Renault Express -22 Window regulator	RENAULT EXPRESS K9K-872 MANUELL	Allbildelar i Huddinge AB - Västerås 010-4974230	3.154 A
2415 7423	W221772 499 SEK	Ford Fiesta -05 Window regulator Right Front	FORD FIESTA V, 5DFORD JH1 FIESTA	Ekholms Bildemontering AB 019-577088	18.331 A
5569 7423	W884446 989 SEK	KIA Carens -14 Window regulator	1.7 CRDI D4FD 1.7 CRDI D4FD MANUELL 2WD 5DR MPV DIE F.V	Østfold bildemontering AS (0047) -69127222	13.939 A
5569 7423	W884571 989 SEK	KIA Carens -14 Window regulator	1.7 CRDI D4FD 1.7 CRDI D4FD MANUELL 2WD 5DR MPV DIE F.H	Østfold bildemontering AS (0047) -69127222	13.939 A
5569 7423	W884520 989 SEK	KIA Carens -14 Window regulator	1.7 CRDI D4FD 1.7 CRDI D4FD MANUELL 2WD 5DR MPV DIE B.V	Østfold bildemontering AS (0047) -69127222	13.939 A
5569 7423	W884566 989 SEK	KIA Carens -14 Window regulator	1.7 CRDI D4FD 1.7 CRDI D4FD MANUELL 2WD 5DR MPV DIE B.H	Østfold bildemontering AS (0047) -69127222	13.939 A
1317 7423	W58327 750 SEK	Audi A4, S4 -99 Window regulator	AUDI A4 1,8 APT M 4DR SED BENSIN	Nordiska Auto Motor AB 0700-175515	- A
1317 7423	W58326 750 SEK	Audi A4, S4 -99 Window regulator	AUDI A4 1,8 APT M 4DR SED BENSIN	Nordiska Auto Motor AB 0700-175515	- A
5060 7423	W1072642 475 SEK	Volvo 940 -91 Window regulator	VOLVO 944-852 GL B230FB T 4DR SED BENSIN VÄNSTER FRAM -1991	Norrbottns Bildemontering AB 0929-70000	30.718 A
5060 7423	W1072644 362 SEK	Volvo 940 -91 Window regulator	VOLVO 944-852 GL B230FB T 4DR SED BENSIN HÖGER FRAM -1991	Norrbottns Bildemontering AB 0929-70000	30.718 A
5060 7423	W1072648 362 SEK	Volvo 940 -91 Window regulator	VOLVO 944-852 GL B230FB T 4DR SED BENSIN VÄNSTER BAK -1991	Norrbottns Bildemontering AB 0929-70000	30.718 A
5060 7423	W1072646 362 SEK	Volvo 940 -91 Window regulator	VOLVO 944-852 GL B230FB T 4DR SED BENSIN HÖGER BAK -1991	Norrbottns Bildemontering AB 0929-70000	30.718 A
1719 7423	W96086 145 SEK	Citroen C3 -05 Window regulator	CITROEN C3 I 1.4I HÖGER BAK	H&K Bildemontering AB 0141-219822	21.399 A
1719 7423	W96085 145 SEK	Citroen C3 -05 Window regulator	CITROEN C3 I 1.4I VÄNSTER BAK	H&K Bildemontering AB 0141-219822	21.399 A
4204 7423	W82480 225 SEK	Skoda Fabia -06 Window regulator	SKODA FABIA I 1.2 VÄNSTER BAK	H&K Bildemontering AB 0141-219822	26.655 A
4218 7423	W736496 500 SEK	Skoda Praktik -15 Window regulator	1.6 TDI DIESEL MINIFLEX 90HK 1.6TDI/CAYB 5VXL 3DR S HF TESTAD OK. HF HF	Vimmerby Bildemontering AB 0492-20028	14.804 A
3826 7423	W676698 1.375 SEK	Renault Clio -13 Window regulator	RENAULT R CLIO H4B-400 5DR CSE BENSIN HÖGER BAK	Allbildelar i Huddinge AB - Västerås 010-4974230	11.345 A
3826 7423	W676697 1.375 SEK	Renault Clio -13 Window regulator	RENAULT R CLIO H4B-400 5DR CSE BENSIN VÄNSTER BAK	Allbildelar i Huddinge AB - Västerås 010-4974230	11.345 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4218 7423	W736495 500 SEK	Skoda Praktik -15 Window regulator	1.6TDI DIESEL MINIFLEX 90HK 1.6TDI/CAYB 5VXL 3DR S VF TESTAD OK. VF VF	Vimmerby Bildemontering AB 0492-20028	14.804 A
4987 7423	W736270	VW Sharan -18 Window regulator	2.0TDI 4-MOTION MPV 184HK 2.0TDI/DFMA AUTOMAT/SCY TESTAD OK. V-SKJUTDÖRR	Vimmerby Bildemontering AB 0492-20028	19.218 A
2978 7423	W5215 400 SEK	Jaguar X-Type -05 Window regulator	JAGUAR X-TYPE I 2.0.D VÄNSTER BAK	H&K Bildemontering AB 0141-219822	31.496 A
2978 7423	W6297 400 SEK	Jaguar X-Type -05 Window regulator	JAGUAR X-TYPE I 2.0.D HÖGER BAK	H&K Bildemontering AB 0141-219822	31.496 A
3827 7423	W675675 1.375 SEK	Renault Clio -19 Window regulator	RENAULT CLIO 5DR CSE BENSIN HÖGER BAK	Allbildelar i Huddinge AB - Västerås 010-4974230	10.685 A
3827 7423	W675644 1.375 SEK	Renault Clio -19 Window regulator	RENAULT CLIO 5DR CSE BENSIN VÄNSTER BAK	Allbildelar i Huddinge AB - Västerås 010-4974230	10.685 A