

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5063 7505	W637607 400 SEK	Volvo V70 -08 Sensor glass breakage	5DCBI 2,4 D5 AUT ABS ESPECC DRAG PDC RÖRELSEGIVARE, IMS, 3 STIFT	Svensk Biläterving AB 019-450690	34.053 A
5576 7505	W618008 2.000 SEK	KIA Cee'd, Cee'd SW -21 Sensor glass breakage	CEED GALE AUTOMAT 5DR STATIONSVAGN KOMBIVAGN ELHYB MED HÅLLARE	Lycksele Bildemontering AB 0950-12140	2.544 A
4929 7505	W1073561	VW Passat -12 Sensor glass breakage	VOLKSWAGEN PASSAT CFGB A 5DR CBI DIESEL ULTRALJUDSSENSOR	Norrbottns Bildemontering AB 0929-70000	23.048 A
5065 7505	W95809 225 SEK	Volvo 960 -96 Sensor glass breakage	VOLVO 960 A-TRAKTOR	H&K Bildemontering AB 0141-219822	- A
5063 7505	W133960	Volvo V70 -11 Sensor glass breakage		AAA Bildemontering i Skutskär AB 026-79100	28.618 A
5076 7505	W42927 300 SEK	Volvo XC60 -17 Sensor glass breakage	VOLVO XC60 D4204T14 A 5DR DIESEL	Eskilstuna Bildemontering AB 016-139906	10.215 A
5575 7505	W131364	KIA Cee'd, Cee'd SW -08 Sensor glass breakage		AAA Bildemontering i Skutskär AB 026-79100	29.877 A
5078 7505	W626427 400 SEK	Volvo V60 -16 Sensor glass breakage	5DCBI 2,4D4 AUT AWD ESPPDC NAV XENON CMBB R-DESI RÖRELSEGIVARE IMS, 3 STIFT	Svensk Biläterving AB 019-450690	19.770 A
5084 7505	W625236 400 SEK	Volvo XC70 -16 Sensor glass breakage	5DCBI 2,4D4 AUT AWD ABSESP PDC ONCALL CMBB NAV RÖRELSEGIVARE IMS	Svensk Biläterving AB 019-450690	18.406 A
4404 7505	W2615022 3.750 SEK	Suzuki Across -22 Sensor glass breakage	SUZUKI ACROSS 4D 2,5 P.IN HYBRID COMBI AWD A25A-FX SIREN, UTAN HÅLLARE	Atracco AB - Växjö 0470-771120	1.818 A
5075 7505	W622126 400 SEK	Volvo XC60 -13 Sensor glass breakage	5DSUV 2,4D4 AUT 4WD ABSESP ECC PDC DRAG RÖRELSEGIVARE IMS, 3 STIFT	Svensk Biläterving AB 019-450690	19.354 A
5575 7505	W31194 225 SEK	KIA Cee'd, Cee'd SW -11 Sensor glass breakage	KIA CEED 1,6 CRDI ECO SW OK	Malmby Bilskrot AB 073-7513592	23.335 A
5575 7505	W126525	KIA Cee'd, Cee'd SW -07 Sensor glass breakage		AAA Bildemontering i Skutskär AB 026-79100	21.308 A
5466 7505	W123523	Lexus IS -15 Sensor glass breakage	ASE301AECILH0 ANTI-HEFT SYSTEM HITH(SRE)amp;NVA SION SENSOR&amp;TILT SENSOR	AAA Bildemontering i Skutskär AB 026-79100	9.523 A
4970 7505	W614453 1.250 SEK	VW Amarok -17 Sensor glass breakage	4DP-U 3,0TDI AUT 4WD ABSESP PDC NAV DRAG XENON ULTRALJUD SENSOR	Svensk Biläterving AB 019-450690	16.230 A
5233 7505	W3627 250 SEK	Hyundai ix20 -10 Sensor glass breakage	HYUNDAI JC	Köpings Bildemontering AB 0221-17933	15.499 A
5025 7505	W37878 200 SEK	Volvo V50 -08 Sensor glass breakage	VOLVO M + V50 D4164T M 5DR DIESEL 3 STIFT	Eskilstuna Bildemontering AB 016-139906	20.513 A
5072 7505	W611891 300 SEK	Volvo S60 -05 Sensor glass breakage	4DSED 2,4 5VXL ABS DSTCECC DRAG RÖRELSEGIVARE, 5 STIFT	Svensk Biläterving AB 019-450690	18.528 A
3639 7505	W116394	Peugeot 5008 -10 Sensor glass breakage	HÖGERSTYRD HÖGERSTYRD	AAA Bildemontering i Skutskär AB 026-79100	- A
4987 7505	W1172107 875 SEK	VW Sharan -12 Sensor glass breakage	VOLKSWAGEN, VW 7N SHARAN CFFB AUTOMAT 5DR DIESEL ULTRALJUDSENSOR	Allbildelar i Huddinge AB 010-4974200	28.309 A
1366 7505	W645147 1.500 SEK	Audi A8, S8 -14 Sensor glass breakage	AUDI A8 3.0D QUATTRO SEDAN 4D CTBA AUTOMAT 4DR SED STÖLDSKYDD INFRARÖD SENSOR	Växjö Bildemontering AB 0470-709650	16.741 A
2517 7505	W409055 3.000 SEK	Cadillac STS Seville -06 Sensor glass breakage	STS 3,6 AUT 4DR SED INTRUSION SENSOR I TAKET	USA Bildelar AB 0479-15540	4.221 A
5064 7505	W606578 400 SEK	Volvo V70 -15 Sensor glass breakage	5DCBI 2,0 D4 AUT ABS ESPECC DRAG PDC ONCALL XENON RÖRELSEGIVARE, IMS, 3 STIFT	Svensk Biläterving AB 019-450690	21.927 A
5076 7505	W1720171 350 SEK	Volvo XC60 -17 Sensor glass breakage	XC60 D4 AWD CLASSIC MOMENTUM D4 2,4 TRONIC 5DR SUV	Ådalens Bildemontering AB 0612-12420	5.738 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5076 7505	W1166753 812 SEK	Volvo XC60 -17 Sensor glass breakage	VOLVO XC60 D5244T21 MANUELL 5DR SUV DIESEL RÖRELSEGIVARE MED KÅPA ORG.NR. 39855481	Allbildelar i Huddinge AB 010-4974200	16.677 A
5027 7505	W1048852 775 SEK	Volvo S90, V90 -17 Sensor glass breakage	VOLVO V90 D4204T9 A 5DR CBI DIESEL SENSOR INNERBELYSNING, IMS OMLNR: 31419969	Norrbottns Bildemontering AB 0929-70000	10.851 A
3702 7505	W1165871 812 SEK	Porsche Cayenne -06 Sensor glass breakage	PORSCHE CAYENNE TURBO S M48.50S AUTOMAT JAB 5DR SUV COUPEÖVERVAKNING	Allbildelar i Huddinge AB 010-4974200	23.913 A
4928 7505	W109176	VW Passat -07 Sensor glass breakage		AAA Bildemontering i Skutskär AB 026-79100	23.442 A
5071 7505	W600825 300 SEK	Volvo S60 -03 Sensor glass breakage	4DSED 2,4 5VXL ABS ECCSTC FÄRDD FARTH RÖRELSEGIVARE, 5 STIFT	Svensk Bilåtervinning AB 019-450690	21.928 A
5046 7505	W1046362 775 SEK	Volvo V90 Cross Country -19 Sensor glass breakage	VOLVO V90 CC D4 AUT D4 A 5DR CBI DIESEL	Norrbottns Bildemontering AB 0929-70000	7.000 A