

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3528 8078	W738368	Opel Astra -13 Airbag krocksensor	1.4 TURBO KOMBI 140HK 1.47IA14NET MZ4 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.731 A
3528 8078	W738367 125 SEK	Opel Astra -13 Airbag krocksensor	1.4 TURBO KOMBI 140HK 1.47IA14NET MZ4 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.731 A
1323 8078	W39598 200 SEK	Audi A4, S4 -12 Airbag krocksensor	2.0 TDI DIESEL AVANT 143 CJCA	Nybro Bildemontering AB 0481-66000	23.000 A
4956 8078	W637350 300 SEK	VW Golf Sportsvan -18 Airbag krocksensor	5DK-S 1,2TSI AUT ABSESP I FRAMDÖRR, LIKSIDIG	Svensk Biläterving AB 019-450690	3.516 A
3333 8078	W134750 500 SEK	Mercedes C-Class -04 Airbag krocksensor	MERCEDES-BENZ C 180 KOMP M271.946 M 4DR BENSIN VÄNSTER BAK	Fyrkantens Bildemontering AB 0920-15504	215.268 A
4914 8078	W185975 150 SEK	VW Golf, e-Golf -06 Airbag krocksensor	VW GOLF 1,6 BSE MANUELL 5DR CSE BENSIN FRAM LIKSIDIG	Bidelshuset i Övik AB 0660-70090	- A
4914 8078	W185974 150 SEK	VW Golf, e-Golf -06 Airbag krocksensor	VW GOLF 1,6 BSE MANUELL 5DR CSE BENSIN FRAM LIKSIDIG	Bidelshuset i Övik AB 0660-70090	- A
4928 8078	W32415 300 SEK	VW Passat -10 Airbag krocksensor Rear	VOLKSWAGEN, VW 3C OK	Malmby Bilskrot AB 073-7513592	21.973 A
4928 8078	W32416 300 SEK	VW Passat -10 Airbag krocksensor Rear	VOLKSWAGEN, VW 3C OK	Malmby Bilskrot AB 073-7513592	21.973 A
3514 8078	W133143 300 SEK	Opel Corsa -13 Airbag krocksensor		AB Magnus Bildemontering 0410-44022	20.091 A
2186 8078	W636791 350 SEK	Nissan X-Trail -17 Airbag krocksensor	5DSUV 1,6DCI AUT ABS VSC FRONT SENSOR	Svensk Biläterving AB 019-450690	6.726 A
5025 8078	W37886 49 SEK	Volvo V50 -08 Airbag krocksensor	VOLVO V50 1.6 D DRIVEE MK2	Munkagård Bilskrot AB 0768-795022	32.400 A
5025 8078	W37918 50 SEK	Volvo V50 -08 Airbag krocksensor	VOLVO V50 1.6 D DRIVEE MK2	Munkagård Bilskrot AB 0768-795022	32.400 A
2205 8078	W133071 250 SEK	Fiat Qubo -10 Airbag krocksensor	FIAT QUBO 1.4 8V BIOGAS FWD	AB Magnus Bildemontering 0410-44022	- A
4309 8078	W41043 220 SEK	Subaru Outback -08 Airbag krocksensor	2.0 AWD DIESEL KOMBI 150 EE20 BAK LIKSIDIG	Nybro Bildemontering AB 0481-66000	23.000 A
4309 8078	W41044 220 SEK	Subaru Outback -08 Airbag krocksensor	2.0 AWD DIESEL KOMBI 150 EE20 BAK LIKSIDIG	Nybro Bildemontering AB 0481-66000	23.000 A
4309 8078	W41046 220 SEK	Subaru Outback -08 Airbag krocksensor	2.0 AWD DIESEL KOMBI 150 EE20 BAKRE BAK	Nybro Bildemontering AB 0481-66000	23.000 A
5078 8078	W371549 375 SEK	Volvo V60 -17 Airbag krocksensor	VOLVO V60 D4204T14 MANUELL 6VXL 5DR CBI DIESEL	Granaths Bilskrot AB 046-52375	12.500 A
5562 8078	W21273 400 SEK	KIA Venga -10 Airbag krocksensor Right	KIA VENGA 1.4 CRDI HÖ B-STOLPE	Petterssons Bildemontering i Tomelilla AB 0417-31318	3.000 A
5562 8078	W21272 400 SEK	KIA Venga -10 Airbag krocksensor Right Front	KIA VENGA 1.4 CRDI HÖ FRAM FRONT	Petterssons Bildemontering i Tomelilla AB 0417-31318	3.000 A
5562 8078	W21271 400 SEK	KIA Venga -10 Airbag krocksensor Left Front	KIA VENGA 1.4 CRDI VÄ FRAM FRONT	Petterssons Bildemontering i Tomelilla AB 0417-31318	3.000 A
4224 8078	W737739 250 SEK	Skoda Karoq -20 Airbag krocksensor	2.0 TDI 4X4 CROSSOVER 150HK 2.0TDI/DFFA AUTOMAT/UAU TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.560 A
1339 8078	W636386 350 SEK	Audi A6 / S6, A6 E-Tron -17 Airbag krocksensor	4DSED 2,0TDI AUT ABS ESP I FRAMDÖRR, LIKSIDIG	Svensk Biläterving AB 019-450690	3 A
5032 8078	W636429 500 SEK	Volvo V60 -20 Airbag krocksensor	5DCBI 2,0D3 AUT ABS ESP/PDC NAV LED BLIS VID B-STOLPE, LIKSIDIG	Svensk Biläterving AB 019-450690	10.877 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4224 8078	W737738 250 SEK	Skoda Karoq -20 Airbag krocksensor	2.0TDI 4X4 CROSSOVER 150HK 2.0TDI DFFA AUTOMATUAV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.560 A
1339 8078	W636389 350 SEK	Audi A6 / S6, A6 E-Tron -17 Airbag krocksensor	4DSED 2,0TDI AUT ABS ESP I FRAMDÖRR, LIKSIDIG	Svensk Bilåtervinning AB 019-450690	3 A
5032 8078	W636425 500 SEK	Volvo V60 -20 Airbag krocksensor	5DCBI 2,0D3 AUT ABS ESPDC NAV LED BLIS MONT I FRAMDÖRR, LIKSIDIG	Svensk Bilåtervinning AB 019-450690	10.877 A
5032 8078	W636404 500 SEK	Volvo V60 -20 Airbag krocksensor	5DCBI 2,0D3 AUT ABS ESPDC NAV LED BLIS MONT I FRAMDÖRR, LIKSIDIG	Svensk Bilåtervinning AB 019-450690	10.877 A
5032 8078	W636426 500 SEK	Volvo V60 -20 Airbag krocksensor	5DCBI 2,0D3 AUT ABS ESPDC NAV LED BLIS VID B-STOLPE, LIKSIDIG	Svensk Bilåtervinning AB 019-450690	10.877 A
4927 8078	W159824 1.495 SEK	VW Passat -03 Airbag krocksensor	VOLKSWAGEN PASSAT VARIANT 1.8T 20V VÄNSTER.	Nya Allbilsroten i Norrköping AB 011-167494	- A