

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5071 4649	W541919 175 SEK	Volvo S60 -02 Sensor AC inner temperature	VOLVO R + S60 B5244S2 M56 4DR SED BENSIN	Begagnade Bildelar i Linköping AB / Norrköping 013-100110	- A
1371 4649	W416490 248 SEK	Audi Q4 e-tron -23 Sensor AC inner temperature	AUDI Q4 50 E TRON FZ BM9T AUTOMAT		1.356 A
4928 4649	W32426 200 SEK	VW Passat -10 Sensor AC inner temperature	VOLKSWAGEN, VW 3C OK	Malmby Bilskrot AB 073-7513592	21.973 A
1321 4649	W58900 250 SEK	Audi A4, S4 -06 Sensor AC inner temperature		Nordiska Auto Motor AB 0700-175515	- A
4928 4649	W32411 250 SEK	VW Passat -10 Sensor AC inner temperature	VOLKSWAGEN, VW 3C OK	Malmby Bilskrot AB 073-7513592	21.973 A
4928 4649	W32413 175 SEK	VW Passat -10 Sensor AC inner temperature	VOLKSWAGEN, VW 3C OK	Malmby Bilskrot AB 073-7513592	21.973 A
4928 4649	W32410 250 SEK	VW Passat -10 Sensor AC inner temperature	VOLKSWAGEN, VW 3C OK	Malmby Bilskrot AB 073-7513592	21.973 A
4928 4649	W32412 175 SEK	VW Passat -10 Sensor AC inner temperature	VOLKSWAGEN, VW 3C OK	Malmby Bilskrot AB 073-7513592	21.973 A
4914 4649	W58721 375 SEK	VW Golf, e-Golf -09 Sensor AC inner temperature	VW GOLF VAR. TDI 105 GOLF BLS A 5DR CSE DIESEL	Nordiska Auto Motor AB 0700-175515	174.998 A
5032 4649	W1192078 162 SEK	Volvo V60 -22 Sensor AC inner temperature	1 V60 RECHAR B4204T46 A 5DR CBI ELHYBRID B TEMPERATURGIVARE	Allbildelar i Huddinge AB 010-4974200	23 A
5032 4649	W1192077 162 SEK	Volvo V60 -22 Sensor AC inner temperature	1 V60 RECHAR B4204T46 A 5DR CBI ELHYBRID B TEMPERATURGIVARE	Allbildelar i Huddinge AB 010-4974200	23 A
5032 4649	W636348 150 SEK	Volvo V60 -20 Sensor AC inner temperature	5DCBI 2,0D3 AUT ABS ESPDC NAV LED BLIS GRÅ, 2 STIFT	Svensk Bilätverning AB 019-450690	10.877 A
2996 4649	W413332 1.116 SEK	Jaguar I-Pace -21 Sensor AC inner temperature	JAGUAR I-PACE DH EV320 AUTOMAT 4WD 5DR EL		4.704 A
1522 4649	W659207 125 SEK	BMW 1-Series -16 Sensor AC inner temperature	BMW 1 F20/F21 11-19 B37-D15A MANUELL 5DR STATIONSV	Växjö Bildemontering AB 0470-709650	17.323 A
1345 4649	W58532 250 SEK	Audi A3, S3 -06 Sensor AC inner temperature	AUDI A3 SP-B ATTRAC 1.6 BLF M 5DR CSE BENSIN	Nordiska Auto Motor AB 0700-175515	160.029 A
5060 4649	W32022 400 SEK	Volvo 940 -97 Sensor AC inner temperature	2,3T KOMBI AUT. AC ABS GCP-GIVARE	Lorenssons Metall- & Bilskrot AB 0485-35140	29.378 A
5024 4649	W159453 745 SEK	Volvo V50 -04 Sensor AC inner temperature	2.0D KOMBI MANUELL	Nya Allbilsroten i Norrköping AB 011-167494	- A
4981 4649	W1735330 125 SEK	VW Multivan -18 Sensor AC inner temperature	VOLKSWAGEN, VW MULTIVAN 2,0 TDI TRONIC 4WD DSG ODR BAK	Ådalens Bildemontering AB 0612-12420	7.324 A
4981 4649	W1735362 125 SEK	VW Multivan -18 Sensor AC inner temperature	VOLKSWAGEN, VW MULTIVAN 2,0 TDI TRONIC 4WD DSG ODR	Ådalens Bildemontering AB 0612-12420	7.324 A
4981 4649	W1735363 125 SEK	VW Multivan -18 Sensor AC inner temperature	VOLKSWAGEN, VW MULTIVAN 2,0 TDI TRONIC 4WD DSG ODR	Ådalens Bildemontering AB 0612-12420	7.324 A
4488 4649	W634872 450 SEK	Toyota Camry -19 Sensor AC inner temperature	4DSED 2,5 HYBRID AUT ABS LUFTJONISERARE	Svensk Bilätverning AB 019-450690	19.416 A
5063 4649	W40500 150 SEK	Volvo V70 -07 Sensor AC inner temperature	2.4 D5 DIESEL KOMBI 186HK D5244T4	Nybro Bildemontering AB 0481-66000	- A
2435 4649	W464599	Ford S-MAX -12 Sensor AC inner temperature	S-MAX 2.0 TDCI AUT 5DR CBI DIESEL	Boets Bildemontering AB 0144-20040	13.900 A
2435 4649	W464601	Ford S-MAX -12 Sensor AC inner temperature	S-MAX 2.0 TDCI AUT 5DR CBI DIESEL	Boets Bildemontering AB 0144-20040	13.900 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
2435 4649	W464600	Ford S-MAX -12 Sensor AC inner temperature	S-MAX 2.0 TDCI AUT 5DR CBI DIESEL	Boets Bildemontering AB 0144-20040	13.900 A
5024 4649	W17960 450 SEK	Volvo V50 -05 Sensor AC inner temperature	V50 1.8 FLEXFUEL	Välsta Bildemontering AB 0650-743200	- A
2388 4649	W2519560 480 SEK	Ford Ranger -21 Sensor AC inner temperature Front	FORD RANGER EU 12-23 YN2X AUTOMAT 0DR LASTBIL DIES FRAM	Eklunds Bildelslager i Skövde AB 0500-413845	12.499 A
1321 4649	W136162	Audi A4, S4 -07 Sensor AC inner temperature		AAA Bildemontering i Skutskär AB 026-79100	17.345 A
1321 4649	W136165	Audi A4, S4 -07 Sensor AC inner temperature		AAA Bildemontering i Skutskär AB 026-79100	17.345 A
1321 4649	W136164	Audi A4, S4 -07 Sensor AC inner temperature		AAA Bildemontering i Skutskär AB 026-79100	17.345 A