

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5287 7268	W596439 438 SEK	Hyundai i20 -22 Knock sensor	I20 G3LE AUTOMAT 5DR KOMBI-SEDAN BENSIN	Lycksele Bildemontering AB 0950-12140	900 A
5287 2080	W596432 1.000 SEK	Hyundai i20 -22 Camshaft adjusting valve	I20 G3LE AUTOMAT 5DR KOMBI-SEDAN BENSIN	Lycksele Bildemontering AB 0950-12140	900 A