

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3232 7493	W612393 375 SEK	Mazda CX-60 -22 Other Sensor	CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	1.844 A
3232 7493	W612511 1.375 SEK	Mazda CX-60 -22 Other Sensor Left Rear	CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN KLÄMSKYDDSENSOR, BAKLUCKA VÄNSTER	Lycksele Bildemontering AB 0950-12140	1.844 A
3232 7493	W612524 1.375 SEK	Mazda CX-60 -22 Other Sensor Right Rear	CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN HÖGER KLÄMLIST BAKLUCKA	Lycksele Bildemontering AB 0950-12140	1.844 A
5577 7493	W611903 600 SEK	KIA Cee'd, Cee'd SW -17 Other Sensor	CEED D4FB 5DR STATIONSVAGN KOMBIVAGN DIESEL FÖR DIMLJUS	Lycksele Bildemontering AB 0950-12140	20.250 A
4221 7493	W610502 562 SEK	Skoda Octavia -21 Other Sensor	OCTAVIA 5DTUA AUTOMAT 5DR STATIONSVAGN KOMBIVAGN TRYCKSENSOR PÅ LADDLUFTSKYLARE	Lycksele Bildemontering AB 0950-12140	18.572 A
4221 7493	W610499 562 SEK	Skoda Octavia -21 Other Sensor	OCTAVIA 5DTUA AUTOMAT 5DR STATIONSVAGN KOMBIVAGN TRYCKSENSOR BRÄNSLEFILTER	Lycksele Bildemontering AB 0950-12140	18.572 A
4489 7493	W606771 375 SEK	Toyota Corolla -23 Other Sensor	COROLLA 1,8 SENSOR, CRANK	Lycksele Bildemontering AB 0950-12140	189 A
4999 7493	W587744 5.000 SEK	VW Touareg -18 Other Sensor Right Rear	TOUAREG DENA AUTOMAT 5DR SUV DIESEL HÖGER BAK, SIDE ASSIST	Lycksele Bildemontering AB 0950-12140	9.238 A
4999 7493	W587743 5.000 SEK	VW Touareg -18 Other Sensor Left Rear	TOUAREG DENA AUTOMAT 5DR SUV DIESEL VÄNSTER BAK, SIDE ASSIST	Lycksele Bildemontering AB 0950-12140	9.238 A
4952 7493	W581293 562 SEK	VW Passat -21 Other Sensor	PASSAT DTUA AUTOMAT 5DR CROSS-OVER DIESEL TRYCKSENSOR BRÄNSLEFILTER	Lycksele Bildemontering AB 0950-12140	5.692 A
1343 7493	W580350 562 SEK	Audi A6 / S6, A6 E-Tron -23 Other Sensor	A6 AVANT DTPA AUTOMAT 5DR KOMBI ELHYBRID DIESEL TRYCKSENSOR PÅ LADDLUFTSKYLARE	Lycksele Bildemontering AB 0950-12140	1.019 A
1308 7493	W580061 625 SEK	Audi A4, S4 -23 Other Sensor	A4 40 TFSI MILD HYBRID DMSA AUTOMAT KOMBI TRYCKSENSOR PÅ GRENRÖR	Lycksele Bildemontering AB 0950-12140	95 A
3288 7493	W572366 100 SEK	Mercedes GLE-Class -22 Other Sensor	-BENZ GLE 400 D 4MATIC OM656.929 AUTOMAT 5DR SUV D TEMPERATURESENSOR	Lycksele Bildemontering AB 0950-12140	1.204 A
4999 7493	W560554 500 SEK	VW Touareg -21 Other Sensor	TOUAREG R DCBE AUTOMAT 5DR SUV ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	2.611 A
1518 7493	W553210 402 SEK	BMW X3 -21 Other Sensor	X3 XDRIVE20D B47-D20B AUTOMAT 5DR SUV DIESEL BROMSPEDALSVÄGSENSOR	Lycksele Bildemontering AB 0950-12140	735 A
5586 7493	W546883 375 SEK	KIA Niro -21 Other Sensor	NIRO EM16 AUTOMAT 5DR CROSS-OVER EL VF/HF-DÖRR KROCKSENSOR	Lycksele Bildemontering AB 0950-12140	872 A
5586 7493	W546875 375 SEK	KIA Niro -21 Other Sensor	NIRO EM16 AUTOMAT 5DR CROSS-OVER EL VF/HF FRAM KROCKSENSOR	Lycksele Bildemontering AB 0950-12140	872 A
1366 7493	W517356 2.835 SEK	Audi A8, S8 -14 Other Sensor Left Rear	AUDI A8 CTEC AUTOMAT 4DR SEDAN DIESEL VÄNSTER BAK	Lycksele Bildemontering AB 0950-12140	11.080 A
3515 7493	W513186 375 SEK	Opel Corsa -17 Other Sensor	CORSA-E 1,4 5 VXL MANUELL UNDERTRYCK, MED SLANG	Lycksele Bildemontering AB 0950-12140	15 A
5574 7493	W505809 6.250 SEK	KIA Optima -18 Other Sensor	KIA OPTIMA 6GANG AUTOMAT 5DR KOMBI ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	2.013 A
2807 7493	W491309 338 SEK	Isuzu D-Max -16 Other Sensor	ISUZU 4JK1-TC AUTOMAT ODR P-U DIESEL AIR DUCT, SENSOR	Lycksele Bildemontering AB 0950-12140	3.063 A
4949 7493	W477962 350 SEK	VW Golf, e-Golf -14 Other Sensor	VOLKSWAGEN VV AU GOLF C/JZA MANUELL 5DR KOMBI-SED INSUG/TRYCKRÖR	Lycksele Bildemontering AB 0950-12140	8.345 A
1516 7493	W472343 150 SEK	BMW X1 -12 Other Sensor	BMW X1 E84 10-15 MANUELL 5DR STATIONSVAGN KOMBIVAG	Lycksele Bildemontering AB 0950-12140	14.465 A
2439 7493	W464621 3.000 SEK	Ford Kuga -17 Other Sensor Left Rear	FORD KUGA T8MA AUTOMAT 5DR SUV DIESEL VÄNSTER BAK	Lycksele Bildemontering AB 0950-12140	1.419 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
2439 7493	W464622 3.000 SEK	Ford Kuga -17 Other Sensor Right Rear	FORD KUGA T8MA AUTOMAT 5DR SUV DIESEL HÖGER BAK	Lycksele Bildmontering AB 0950-12140	1.419 A
4220 7493	W455399 1.250 SEK	Skoda Superb -17 Other Sensor Left Rear	SUPERB DFCA A 5DR KOMBI-SEDAN DIESEL FILBYTESASSISTENT	Lycksele Bildmontering AB 0950-12140	3.006 A
4518 7493	W389530 300 SEK	Toyota RAV 4 -18 Other Sensor	TOYOTA TOYOTA RAV4 VARIOMATIC 5DR SUV ELHYBRID BEN DÄCKTRYCK	Lycksele Bildmontering AB 0950-12140	498 A
4518 7493	W389529 300 SEK	Toyota RAV 4 -18 Other Sensor	TOYOTA TOYOTA RAV4 VARIOMATIC 5DR SUV ELHYBRID BEN DÄCKTRYCK	Lycksele Bildmontering AB 0950-12140	498 A
2163 7493	W364161 500 SEK	Nissan Leaf -15 Other Sensor	LEAF EM61 5DR KOMBI-SEDAN EL BRAKE STOKE SENSOR	Lycksele Bildmontering AB 0950-12140	4.008 A
5027 7493	W549938 800 SEK	Volvo S90, V90 -17 Other Sensor	V90 D4204T14 AUTOMAT 5DR KOMBI DIESEL	Lycksele Bildmontering AB 0950-12140	13.566 A