

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
1760 7116	W428749	Citroen C1 -08 Hub rear Rear	1.0I SX 68HK 1,0I/CFA 5VXL 5DR CC BENSIN TESTAD, OK! HÖGER. MED ABS GIVARE	Vimmerby Bildemontering AB 0492-20028	6.573 A
1760 7116	W428750	Citroen C1 -08 Hub rear Rear	1.0I SX 68HK 1,0I/CFA 5VXL 5DR CC BENSIN TESTAD, OK! VÄNSTER, MED ABS GIVARE	Vimmerby Bildemontering AB 0492-20028	6.573 A
1760 7116	W428223	Citroen C1 -06 Hub rear Rear	1,0 68HK 1,0I/CFA 5VXL 5DR CC BENSIN TESTAD, OK! MED ABS GIVARE (H.BAK)	Vimmerby Bildemontering AB 0492-20028	11.940 A
1760 7116	W428222	Citroen C1 -06 Hub rear Rear	1,0 68HK 1,0I/CFA 5VXL 5DR CC BENSIN TESTAD, OK! MED ABS GIVARE (V.BAK)	Vimmerby Bildemontering AB 0492-20028	11.940 A
1760 7116	W599842	Citroen C1 -10 Hub rear Rear	1.0I KOMBI-SEDAN 68HK 1.0I/CFA AUTOMAT 5DR CC BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A
1760 7116	W599843	Citroen C1 -10 Hub rear Rear	1.0I KOMBI-SEDAN 68HK 1.0I/CFA AUTOMAT 5DR CC BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A