

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3528 3007	W544375 200 SEK	Opel Astra -15 Handle exterior Left	1.6CDTI DIESEL KOMBI 110HK 1.6CDTI/B16DTL 6VXL 5DR V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	7.443 A
3528 3007	W532777 200 SEK	Opel Astra -10 Handle exterior Left	1.7CDTI DIESEL 125HK 1.7CDTI/A17DTR 6VXL/MZ4 5DR CC V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	17.164 A
3528 3007	W532778 200 SEK	Opel Astra -10 Handle exterior Left	1.7CDTI DIESEL 125HK 1.7CDTI/A17DTR 6VXL/MZ4 5DR CC V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	17.164 A
3528 3007	W515695 200 SEK	Opel Astra -10 Handle exterior Left	1.6-16V 116HK 1.6/A16XER MANUELL 5DR CSE BENSIN V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	14.310 A
3528 3007	W515694 200 SEK	Opel Astra -10 Handle exterior Left	1.6-16V 116HK 1.6/A16XER MANUELL 5DR CSE BENSIN V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	14.310 A
3528 3007	W684195	Opel Astra -13 Handle exterior Left	1.7 CDTI DIESEL KOMBI 110HK 1.7 CDTI/A17DTE 5DR HGV V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	18.108 A
3528 3007	W684196	Opel Astra -13 Handle exterior Left	1.7 CDTI DIESEL KOMBI 110HK 1.7 CDTI/A17DTE 5DR HGV V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	18.108 A
3528 3007	W683466	Opel Astra -12 Handle exterior Left	1.7 CDTI DIESEL KOMBI 110HK 1.7/A17DTC 6VXL 5DR HGV V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	24.086 A
3528 3007	W650280	Opel Astra -15 Handle exterior Left	1.6CDTI DIESEL KOMBI 110HK 1.6CDTI/B16DTL 6VXL 5DR V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	5.924 A
3528 3007	W641334	Opel Astra -11 Handle exterior Left	1.3CDTI DIESEL CC 95HK 1.3CDTI/A13DTE 6VXL 5DR CC D V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	15.340 A
3528 3007	W641338	Opel Astra -11 Handle exterior Left	1.3CDTI DIESEL CC 95HK 1.3CDTI/A13DTE 6VXL 5DR CC D V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	15.340 A
3528 3007	W633705	Opel Astra -11 Handle exterior Left	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	16.987 A
3528 3007	W633706	Opel Astra -11 Handle exterior Left	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	16.987 A
3528 3007	W603673	Opel Astra -11 Handle exterior Left	1.7CDTI KOMBI-SEDAN 125HK 1.7CDTI/A17DTR 6VXL 5DR C V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	15.092 A
3528 3007	W603672	Opel Astra -11 Handle exterior Left	1.7CDTI KOMBI-SEDAN 125HK 1.7CDTI/A17DTR 6VXL 5DR C V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	15.092 A
3528 3007	W597790	Opel Astra -15 Handle exterior Left	1.4I TURBO KOMBI 140HK 1.4I/B14NET MZ4 5DR HGV BENS V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	6.624 A
3528 3007	W597791	Opel Astra -15 Handle exterior Left	1.4I TURBO KOMBI 140HK 1.4I/B14NET MZ4 5DR HGV BENS V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	6.624 A
3528 3007	W570887	Opel Astra -11 Handle exterior Left	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR V.BAK TESTAD OK V.BAK	Vimmerby Bildemontering AB 0492-20028	13.310 A
3528 3007	W570889	Opel Astra -11 Handle exterior Left	1.7CDTI DIESEL KOMBI 125HK 1.7CDTI/A17DTR 6VXL 5DR V.FRAM TESTAD OK V.FRAM	Vimmerby Bildemontering AB 0492-20028	13.310 A