

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
2791 3007	W580209	Honda CR-V -14 Handle exterior Left	2.2CDTI DIESEL SUV 150HK 2.2CDTIN22B4 6VXL 5DR SUV FRAM TESTAD OK FRAM	Vimmerby Bildemontering AB 0492-20028	26.765 A
2791 3007	W580210	Honda CR-V -14 Handle exterior Left	2.2CDTI DIESEL SUV 150HK 2.2CDTIN22B4 6VXL 5DR SUV BAK TESTAD OK BAK	Vimmerby Bildemontering AB 0492-20028	26.765 A
2791 3007	W631817	Honda CR-V -13 Handle exterior Left	2.2CTDI DIESEL SUV 150HK 2.2CTDIN22B4 6VXL 5DR SUV BAK TESTAD OK BAK	Vimmerby Bildemontering AB 0492-20028	12.345 A
2791 3007	W631814	Honda CR-V -13 Handle exterior Left	2.2CTDI DIESEL SUV 150HK 2.2CTDIN22B4 6VXL 5DR SUV BAK TESTAD OK BAK	Vimmerby Bildemontering AB 0492-20028	12.345 A