

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3428 3220	W599452	Mitsubishi ASX -13 Combined Instrument	1.8DI-D DIESEL SUV 116HK 1.8DID/4N13 6VXL 5DR SUV D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.473 A
3428 3220	W591146	Mitsubishi ASX -11 Combined Instrument	1.8DI-D DIESEL 4WD SUV 150HK 1.8D/4N13 6VXL 5DR SUV	Vimmerby Bildemontering AB 0492-20028	15.700 A
3428 3220	W578509	Mitsubishi ASX -11 Combined Instrument	1.6I 117HK SUV 1.6I/4A92 5VXL 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	11.900 A
3428 3220	W527525	Mitsubishi ASX -12 Combined Instrument	1,8 DI-D DIESEL 4WD 116HK 1,8D/4N13 6VXL/W6MBA 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.619 A
3428 3220	W451023	Mitsubishi ASX -11 Combined Instrument	1,6I/4A92 5VXL 5DR SUV BENSIN TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.080 A