

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
2791 3008	W631815	Honda CR-V -13 Handle exterior Right	2.2CTDI DIESEL SUV 150HK 2.2CTDIN22B4 6VXL 5DR SUV BAK TESTAD OK BAK	Vimmerby Bildemontering AB 0492-20028	12.345 A
2791 3008	W631816	Honda CR-V -13 Handle exterior Right	2.2CTDI DIESEL SUV 150HK 2.2CTDIN22B4 6VXL 5DR SUV FRAM TESTAD OK FRAM	Vimmerby Bildemontering AB 0492-20028	12.345 A
2791 3008	W580208	Honda CR-V -14 Handle exterior Right	2.2CDTI DIESEL SUV 150HK 2.2CDTIN22B4 6VXL 5DR SUV BAK TESTAD OK BAK	Vimmerby Bildemontering AB 0492-20028	26.765 A
2791 3008	W580207	Honda CR-V -14 Handle exterior Right	2.2CDTI DIESEL SUV 150HK 2.2CDTIN22B4 6VXL 5DR SUV FRAM TESTAD OK FRAM	Vimmerby Bildemontering AB 0492-20028	26.765 A