

| VCode PCode | Stock no. Price | Vehicle Part | Vehicle Information Part Information | Company Phone | Milage Quality |
|----------------|--------------------|-------------------------------|---|--|-------------------|
| 5053 7463 | W635675 | Volvo C30 -11 Lambda probe | 1.6D D2 SPORTCOUPE 114HK 1.6D/D4162T 6VXL 3DR CC DI FRÄMRE TESTAD OK FRÄMRE | Vimmerby Bildemontering AB 0492-20028 | 15.170 A |
| 5053 7463 | W509843 | Volvo C30 -11 Lambda probe | 1.6D2 114HK 1.6D2/D4162T 6VXL/B6 3DR CC DIESEL TESTAD OK | Vimmerby Bildemontering AB 0492-20028 | 14.633 A |
| 5053 7463 | W626984 | Volvo C30 -11 Lambda probe | 1.6D D2 DIESEL SPORTCOUPE 114HK 1.6D/D4162T 6VXL 3DR FRÄMRE TESTAD OK FRÄMRE | Vimmerby Bildemontering AB 0492-20028 | 25.022 A |