

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5053 5025	W635686	Volvo C30 -11 Rear sensor	1.6D D2 SPORTCOUPE 114HK 1.6D/D4162T 6VXL 3DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.170 A
5053 5025	W635688	Volvo C30 -11 Rear sensor	1.6D D2 SPORTCOUPE 114HK 1.6D/D4162T 6VXL 3DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.170 A
5053 5025	W635689	Volvo C30 -11 Rear sensor	1.6D D2 SPORTCOUPE 114HK 1.6D/D4162T 6VXL 3DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.170 A
5053 5025	W635687	Volvo C30 -11 Rear sensor	1.6D D2 SPORTCOUPE 114HK 1.6D/D4162T 6VXL 3DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.170 A