

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5319 7463	W636355	Seat Arona -20 Lambda probe	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG BAKRE TESTAD OK BAKRE	Vimmerby Bildemontering AB 0492-20028	- A
5319 7463	W636356	Seat Arona -20 Lambda probe	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG FRÄMRE TESTAD OK FRÄMRE	Vimmerby Bildemontering AB 0492-20028	- A
5319 7463	W724430	Seat Arona -19 Lambda probe	1.0 TSI CROSSOVER 95HK 1.0DKLA 5VXL 5DR SUV BENSIN FRÄMRE TESTAD OK FRÄMRE	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7463	W724428	Seat Arona -19 Lambda probe	1.0 TSI CROSSOVER 95HK 1.0DKLA 5VXL 5DR SUV BENSIN BAKRE TESTAD OK BAKRE	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7463	W708554	Seat Arona -19 Lambda probe	1.0 TSI CROSSOVER 70HK 1.0TSI/DKLA 5VXL 5DR SUV BEN BAKRE TESTAD OK BAKRE	Vimmerby Bildemontering AB 0492-20028	7.900 A