

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5319 5025	W636365 100 SEK	Seat Arona -20 Rear sensor	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	- A
5319 5025	W636366 375 SEK	Seat Arona -20 Rear sensor	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A
5319 5025	W636362	Seat Arona -20 Rear sensor	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A