

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5319 7310	W724413	Seat Arona -19 Control unit Xenon	1.0 TSI CROSSOVER 95HK 1.0DKLA 5VXL 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7310	W708537	Seat Arona -19 Control unit Xenon	1.0 TSI CROSSOVER 70HK 1.0TSIDKLA 5VXL 5DR SUV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.900 A
5319 7310	W636359	Seat Arona -20 Control unit Xenon	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A
5319 7310	W636358	Seat Arona -20 Control unit Xenon	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK! HÖGER	Vimmerby Bildemontering AB 0492-20028	- A