

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3528 7255	W738309	Opel Astra -13 Turbo aggregate	1.4 TURBO KOMBI 140HK 1.47A14NET MZ4 5DR HGV BENSI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.731 A
2499 7255	W738222	Ford Transit Connect/Tourneo Connect -16 Turbo aggregate	1.5 TDCI DIESEL MINIFLEX 120HK 1.5TDCI/XWGA 6VXL/B6 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	12.736 A
3895 7255	W738092 3.750 SEK	Renault Master -11 Turbo aggregate	2.3 DCI FLAK/CHASSI 146HK 2.3DCI/M9T-6 6VXL/PF6 ODR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	23.767 A
4987 7255	W738049	VW Sharan -17 Turbo aggregate	2.0 TDI 4-MOTION MPV 184HK 2.0TDI/DFMA AUTOMAT/SCY TESTAD OK	Vimmerby Bildemontering AB 0492-20028	36.837 A
4972 7255	W737951 6.000 SEK	VW Caddy -17 Turbo aggregate	2.0 TDI MINIFLEX SKÅP 102HK 2.0TDI/DFSD 5VXL/RTH 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	16.842 A
3679 7255	W737878	Peugeot Boxer -18 Turbo aggregate	2.0 HDI DIESEL FLAK/CHASSI 2.0HDI/AHN 6VXL ODR PIC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.800 A
4224 7255	W737682	Skoda Karoq -20 Turbo aggregate	2.0 TDI 4X4 CROSSOVER 150HK 2.0TDI/DFFA AUTOMAT/UAU TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.560 A
1540 7255	W737425	BMW 5-Series -16 Turbo aggregate	520 2.0D XDRIVE TOURING 190HK 2.0D/B47-D20A AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.128 A
5291 7255	W737522 800 SEK	Hyundai i30 -14 Turbo aggregate	1.6 CRDI KOMBI-SEDAN 110HK 1.6CRDI/D4FB 6VXL 5DR CS TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.668 A
5576 7255	W737281 10.000 SEK	KIA Cee'd, Cee'd SW -19 Turbo aggregate	1.6 CRDI SPORTWAGON 136HK 1.6CRDI/D4FE AUTOMAT/HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	5.802 A
2499 7255	W737077 6.750 SEK	Ford Transit Connect/Tourneo Connect -21 Turbo aggregate	1.5 ECOBLUE MINIFLEX SKÅP 101HK Z2GA AUTOMAT/8F35 3D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	5.487 A
3827 7255	W736776	Renault Clio -19 Turbo aggregate	0.9 TCE KOMBI-SEDAN 90HK 0.9/H4B-408 5VXL/JH3 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.702 A
4972 7255	W736595 3.000 SEK	VW Caddy -17 Turbo aggregate	1.4 TSI CNG MINIFLEX SKÅP 110HK CPWA 6VXL 5DR SKP BI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.006 A
4218 7255	W736502 3.250 SEK	Skoda Praktik -15 Turbo aggregate	1.6 TDI DIESEL MINIFLEX 90HK 1.6TDI/CAYB 5VXL 3DR S TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.804 A
4411 7255	W736136 5.500 SEK	Suzuki SX4 S-Cross -17 Turbo aggregate	1.0 ALLGRIP SUV 112HK 1.0/K10C MANUELL 5DR SUV BENS TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.361 A
5028 7255	W736009	Volvo V40 12-19 -16 Turbo aggregate	2.0 D3 DIESEL KOMBI 150HK 2.0/D4204T9 6VXL 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.391 A
5028 7255	W735913	Volvo V40 12-19 -13 Turbo aggregate	1.6 D2 DIESEL KOMBI 114HK 1.6/D4162T 6VXL/B6 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.316 A
4953 7255	W735661	VW Polo -19 Turbo aggregate	1.0 TSI KOMBI-SEDAN 1.0/DKLA 5VXL/SJD 5DR CC BENSI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.219 A
2118 7255	W735468	Nissan Juke -15 Turbo aggregate	1.2 DIG-T CROSSOVER 116HK 1.2/HRA2DDT 6VXL/HRA2DDT. TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.633 A
3862 7255	W735498	Renault Megane -18 Turbo aggregate	1.5 DCI DIESEL GRANDTOUR 110HK 1.5DCI/K9K-657 6VXL 5 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.803 A
4303 7255	W735315	Subaru Outback -10 Turbo aggregate	2.0 DIESEL AWD CROSSOVER 150HK 2.0/EE20 6VXL 5DR SU TESTAD OK	Vimmerby Bildemontering AB 0492-20028	24.453 A
3312 7255	W735074	Mercedes A-Class -13 Turbo aggregate	A180 1.5CDI MINIFLEX 109HK 1.5/OM607.951 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.038 A
3827 7255	W735062 2.500 SEK	Renault Clio -17 Turbo aggregate	0.9 TCE KOMBI-SEDAN 90HK 0.9/H4B 5VXL/JH3 5DR CSE B TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.672 A
2165 7255	W734944 1.500 SEK	Nissan Navara -06 Turbo aggregate	2.5DCI 4WD DIESEL PICKUP 2.5DCI/YD25DDT1 5VXL ODR P TESTAD OK	Vimmerby Bildemontering AB 0492-20028	29.186 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5014 7255	W734868	Volvo S60 Cross Country -16 Turbo aggregate	2.4 D5 DIESEL AWD CROSSOVER 2.4D5/D5244T21 6-AUT 4W TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.162 A
3827 7255	W733010 3.750 SEK	Renault Clio -18 Turbo aggregate	1.5 DCI DIESEL KOMBI-SEDAN 1.5DCI/K9K628 5VXL/JR506 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	11.678 A
4213 7255	W732424 7.000 SEK	Skoda Fabia -18 Turbo aggregate	1.0 TSI KOMBI-SEDAN 1.0VCHZB 5VXL/QTS 5DR CC BENSJ TESTAD OK	Vimmerby Bildemontering AB 0492-20028	11.069 A
4949 7255	W732372	VW Golf, e-Golf -18 Turbo aggregate	2.0 GTD 4M CROSSOVER 184HK 2.0DCCA AUTOMAT 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	5.915 A
1531 7255	W731989 10.000 SEK	BMW 3-Series -16 Turbo aggregate	320 2.0I XDRIVE F30 184HK 2.0VBA8-B20A AUTOMAT 4DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.892 A
2959 7255	W731651	Iveco Daily -15 Turbo aggregate	2.3HPT DIESEL SKÄPKOMBI 146HK 2.3F1AFL411C 6VXL 0 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	16.964 A