

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
9555 9709	W1731944 3.750 SEK	Scania Lastbil -17 Refrigerator	SCANIA S580 B6X2*4NB DC16 106 L01 GRS0925R TMS2 SCA DEFEKT LÅSNING & SKADAT LOCK SE BILD KYLSKÅP	Ådalens Bildmontering AB 0612-12420	110.000 M
9555 9709	W1731948 3.750 SEK	Scania Lastbil -17 Refrigerator	SCANIA S580 B6X2*4NB DC16 106 L01 GRS0925R TMS2 SCA DEFEKT LOCK SE BILD. TESTAT KYLSKÅP	Ådalens Bildmontering AB 0612-12420	110.000 M
9554 9709	W1731234 6.250 SEK	Mercedes Lastbil -21 Refrigerator	MERCEDES-BENZ ACTROS 473909 715523 MB ACTROS EJ TESTAD KYLSKÅP	Ådalens Bildmontering AB 0612-12420	24.000 A*
9555 9709	W1730886 7.500 SEK	Scania Lastbil -12 Refrigerator	SCANIA R560LA6X2MNA DC16 18 L01 56 GRS905R OPC5 SCA REPIG KYLSKÅP	Ådalens Bildmontering AB 0612-12420	91.700 A*
9555 9709	W1730884 7.500 SEK	Scania Lastbil -07 Refrigerator	SCANIA R480 LB6X2MNB DC13 07 L01 480 GRS905 SCANIA REPIG KYLSKÅP	Ådalens Bildmontering AB 0612-12420	- A*
9556 9709	W1712342 8.750 SEK	Volvo Lastbil -14 Refrigerator	FH 510 6X2 D13C500 AUTOMAT VOLVO FH EJ TESTAD. REPIG FRAMSIDA KYLSKÅP	Ådalens Bildmontering AB 0612-12420	180.000 A*
9555 9709	W1712304	Scania Lastbil -13 Refrigerator	R560LA6X2HNA DC16 18/560 GRS905R OPC5 SCANIA R-SERI KYLSKÅP	Ådalens Bildmontering AB 0612-12420	89.141 A
9556 9709	W1712281	Volvo Lastbil -13 Refrigerator	VOLVO FH16 8*4 D16G 600 ATO3112D VOLVO FH EJ TESTAD. DEFEKT KONTAKT SE BILD KYLSKÅP	Ådalens Bildmontering AB 0612-12420	55.000 A*
9555 9709	W1608644 625 SEK	Scania Lastbil -10 Refrigerator	FÄSTE KYLSKÅP	Ådalens Bildmontering AB 0612-12420	- A