

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5060 7125	W1071965	Volvo 940 -91 Anti-Roll Cross bar Rear	VOLVO 944-852 GL B230FB T 4DR SED BENSIN	Norrbottens Bildemontering AB 0929-70000	30.718 A
5296 7125	W903694 295 SEK	Hyundai H-1/Starex -15 Anti-Roll Cross bar Rear	HYUNDAI H-1 2.5 CRDI 136HK 6VXL 4DR SKP DIESEL	Norrbottens Bildemontering AB 0929-70000	8.759 A*
5290 7125	W662067 225 SEK	Hyundai i30 -12 Anti-Roll Cross bar Rear	HYUNDAI I30 KOMBI, 5D CW 1.6 CRDI 5VXL 5DR CBI DIES	Norrbottens Bildemontering AB 0929-70000	300 A
5290 7125	W662068 225 SEK	Hyundai i30 -12 Anti-Roll Cross bar Rear	HYUNDAI I30 KOMBI, 5D CW 1.6 CRDI 5VXL 5DR CBI DIES	Norrbottens Bildemontering AB 0929-70000	300 A
1338 7125	W338134 196 SEK	Audi A6 / S6, A6 E-Tron -07 Anti-Roll Cross bar Rear	2,0T 2,0T FSI 6VXL 2WD CBI BENSIN LIKSIDIG KOPPLINGSSTÅNG	Norrbottens Bildemontering AB 0929-70000	3.141 A
2523 7125	W304568 395 SEK	Chevrolet Corvette -99 Anti-Roll Cross bar Rear	CORVETTE C5 5,7 V8 AUT SCP BENSIN HÖGER HÖGER	Norrbottens Bildemontering AB 0929-70000	12.455 A
2523 7125	W304569 395 SEK	Chevrolet Corvette -99 Anti-Roll Cross bar Rear	CORVETTE C5 5,7 V8 AUT SCP BENSIN VÄNSTER VÄNSTER	Norrbottens Bildemontering AB 0929-70000	12.455 A