

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
3313 3204	W1075101	Mercedes GLK-Class -09 Instrument border	MERCEDES-BENZ GLK 350 M272.971 A 5DR SUV BENSIN	Norrbottens Bildemontering AB 0929-70000	15.481 A*
5085 3204	W1069435	Volvo XC40 -22 Instrument border	VOLVO XC40 B3154T9 A SUV	Norrbottens Bildemontering AB 0929-70000	3.491 A*
5032 3204	W1068752 212 SEK	Volvo V60 -22 Instrument border	VOLVO V60 B4204T52 A CBI MED ÖVRE RATTKÅPA 31498499	Norrbottens Bildemontering AB 0929-70000	4.126 A
3449 3204	W1066775 995 SEK	Mitsubishi Outlander -20 Instrument border	MITSUBISHI OUTLANDER 4B12 A 5DR SUV ELHYBRID B	Norrbottens Bildemontering AB 0929-70000	4.174 A
4217 3204	W1066434 200 SEK	Skoda Kodiaq -20 Instrument border	SKODA KODIAQ DFHA A 5DR SUV DIESEL VÄRMEREGGLAGE	Norrbottens Bildemontering AB 0929-70000	12.634 A*
5064 3204	W1066345 150 SEK	Volvo V70 -15 Instrument border	VOLVO V70 D5244T12 A 5DR CBI DIESEL RAM TILL PANEL PÅ TUNNELKONSOL	Norrbottens Bildemontering AB 0929-70000	17.253 A
5015 3204	W1062758 190 SEK	Volvo V60 Cross Country -21 Instrument border	VOLVO V60 CC 2.0D B4 2.0D B4 AUT 4WD 5DR CBI ELHYBR MED ÖVRE RATTKÅPA 31498499	Norrbottens Bildemontering AB 0929-70000	11.557 A
5064 3204	W1060303 100 SEK	Volvo V70 -14 Instrument border	VOLVO V70 D4 2.0 6VXL 2WD 5DR CBI DIESEL RAM TILL PANEL PÅ TUNNELKONSOL	Norrbottens Bildemontering AB 0929-70000	22.132 A
5084 3204	W1060117 400 SEK	Volvo XC70 -16 Instrument border	VOLVO XC70 D4 D5244T12 A 5DR CBI DIESEL TILL FÄRDDATOR	Norrbottens Bildemontering AB 0929-70000	9.025 A
4490 3204	W1058997 335 SEK	Toyota RAV 4 -22 Instrument border	TOYOTA RAV 4 2.5I HYBRID AUT HYBRID 5DR SUV ELHYBRI INSTRUMENT PANEL FÖR STRÖMSTÄLLARE STOL AIRBAG	Norrbottens Bildemontering AB 0929-70000	831 A*
5046 3204	W1058213 160 SEK	Volvo V90 Cross Country -22 Instrument border	VOLVO V90 CC D420T8 A 5DR CBI ELHYBRID D MED INSYNSSKYDD OCH KÅPA	Norrbottens Bildemontering AB 0929-70000	224 A
5060 3204	W1058033 150 SEK	Volvo 940 -95 Instrument border	VOLVO 945-811 S 2.3 B230FK M 5DR CBI BENSIN REGLAGEPANEL LJUSREGLAGE, SVART	Norrbottens Bildemontering AB 0929-70000	35.147 A
2781 3204	W1057936 595 SEK	Honda HR-V -19 Instrument border	HONDA HR-V 1,5I 131HK 6VXL 5DR SUV BENSIN SARG TILL VÄNSTER DEFROSTERKANAL	Norrbottens Bildemontering AB 0929-70000	4.951 A*
2781 3204	W1057920 1.800 SEK	Honda HR-V -19 Instrument border	HONDA HR-V 1,5I 131HK 6VXL 5DR SUV BENSIN	Norrbottens Bildemontering AB 0929-70000	4.951 A*
4486 3204	W1057094 335 SEK	Toyota Hilux -21 Instrument border	TOYOTA HILUX 1GD-FTV A 0DR PIC DIESEL	Norrbottens Bildemontering AB 0929-70000	6.174 A*
5079 3204	W1056045 100 SEK	Volvo V60 Cross Country -16 Instrument border	VOLVO V60 CROSS COUNTRY D5244T21 AUT 5DR CBI DIESEL RAM TILL PANEL PÅ TUNNELKONSOL	Norrbottens Bildemontering AB 0929-70000	15.508 A*
4971 3204	W1055864 495 SEK	VW Caddy -23 Instrument border	VW CADDY DTRC M SKP RAM MED LUFTUTBLÅS SATINSVART/SVART MED 5G20858660A	Norrbottens Bildemontering AB 0929-70000	1.105 A*
4971 3204	W1055865 115 SEK	VW Caddy -23 Instrument border	VW CADDY DTRC M SKP SATINSVART	Norrbottens Bildemontering AB 0929-70000	1.105 A
8701 3204	W1053033 100 SEK	Ski-Doo Snöskoter -06 Instrument border	RENEGADE 800 HO 800 POWER TEC AUT/VARIATOR SSK RENEGADE 800	Norrbottens Bildemontering AB 0929-70000	445 A
5083 3204	W1048714 100 SEK	Volvo XC70 -13 Instrument border	VOLVO XC70 2.4D 215HK TIPTRONIC 5DR CBI DIESEL RAM TILL PANEL PÅ TUNNELKONSOL	Norrbottens Bildemontering AB 0929-70000	25.014 A*
4996 3204	W1047970 75 SEK	VW Transporter/Caravelle -11 Instrument border	VW PICKUP DH 2.0 4MOTION 2.0TDI 6VXL 4WD 4DR FLK DI SARG TILL AC STYRENHET 7E5907047AD	Norrbottens Bildemontering AB 0929-70000	30.474 A
8701 3204	W1047219 300 SEK	Ski-Doo Snöskoter -09 Instrument border	SKI-DOO RENEGADE X 1200 1200 SSK RENEGADE 1200, SVART	Norrbottens Bildemontering AB 0929-70000	664 A
5090 3204	W1046289 275 SEK	Volvo XC90 -22 Instrument border	VOLVO XC90 B4204T34 A 5DR SUV ELHYBRID B CHARCOAL	Norrbottens Bildemontering AB 0929-70000	3.160 A
4489 3204	W1045449 295 SEK	Toyota Corolla -21 Instrument border	TOYOTA COROLLA 1.8 CVT HYBRID 1.8 HYBRID CVT 5DR CB REPA SYNS INTE SÅ MYCKET NÄR DEN ÄR MOTERAD	Norrbottens Bildemontering AB 0929-70000	2.499 M

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
5095 3204	W1044962 195 SEK	Volvo XC60 -22 Instrument border	VOLVO XC60 T8 RECHARGE T8 AUT 5DR SUV ELHYBRID B	Norrbottns Bildemontering AB 0929-70000	812 A*
5027 3204	W1044689 160 SEK	Volvo S90, V90 -19 Instrument border	V90 D3 AWD 150HK AUT ADBLUE D3 2,0 150HK AUT AWD 5D	Norrbottns Bildemontering AB 0929-70000	13.850 A
5095 3204	W1044093 400 SEK	Volvo XC60 -22 Instrument border	VOLVO XC60 T8 RECHARGE T8 AUT 5DR SUV ELHYBRID B	Norrbottns Bildemontering AB 0929-70000	812 A
5027 3204	W1043434 160 SEK	Volvo S90, V90 -18 Instrument border	VOLVO V90 D3 GEAR D4204T9 AUTOMAT 5DR CBI DIESEL	Norrbottns Bildemontering AB 0929-70000	7.185 A
2499 3204	W1041776 120 SEK	Ford Transit Connect/Tourneo Connect -23 Instrument border	FORD TRANSIT CONNECT 1,5 TDCI 120HK A 3DR SKP DIESEL VID AC REGLAGE	Norrbottns Bildemontering AB 0929-70000	306 A
5015 3204	W1039211 187 SEK	Volvo V60 Cross Country -20 Instrument border	VOLVO V60 CC D4204T14 A 5DR CBI DIESEL MED ÖVRE RATTKÅPA 31498499	Norrbottns Bildemontering AB 0929-70000	8.602 A