

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4929 7714	W1075310	VW Passat -13 Inter axle Rubber joint	VOLKSWAGEN PASSAT ALLTRACK CFGB A 5DR CBI DIESEL BAKRE KOPPLINGSSKIVA MED UTJÄMNINGSVIKT	Norrbottns Bildemontering AB 0929-70000	24.124 A
4929 7714	W1073651	VW Passat -12 Inter axle Rubber joint	VOLKSWAGEN PASSAT CFGB A 5DR CBI DIESEL BAKRE KOPPLINGSSKIVA MED UTJÄMNINGSVIKT	Norrbottns Bildemontering AB 0929-70000	23.048 A
4217 7714	W1066511 1.995 SEK	Skoda Kodiaq -20 Inter axle Rubber joint	SKODA KODIAQ DFHA A 5DR SUV DIESEL BAK	Norrbottns Bildemontering AB 0929-70000	12.634 A
4217 7714	W1066510 695 SEK	Skoda Kodiaq -20 Inter axle Rubber joint	SKODA KODIAQ DFHA A 5DR SUV DIESEL FRAM	Norrbottns Bildemontering AB 0929-70000	12.634 A
4219 7714	W1039792 595 SEK	Skoda Yeti -17 Inter axle Rubber joint	SKODA YETI DFSA M 5DR CBI DIESEL FRÄMRE PASSAR 1K0521101H	Norrbottns Bildemontering AB 0929-70000	15.295 A
4219 7714	W1039791 1.995 SEK	Skoda Yeti -17 Inter axle Rubber joint	SKODA YETI DFSA M 5DR CBI DIESEL BAKRE KOPPLINGSSKIVA MED UTJÄMNINGSVIKT	Norrbottns Bildemontering AB 0929-70000	15.295 A
4207 7714	W1023306 1.995 SEK	Skoda Superb -14 Inter axle Rubber joint	SKODA SUPERB CFGB DSG 4WD 5DR CBI DIESEL BAKRE KOPPLINGSSKIVA MED UTJÄMNINGSVIKT	Norrbottns Bildemontering AB 0929-70000	15.780 A
4209 7714	W1006102 695 SEK	Skoda Octavia -16 Inter axle Rubber joint	SKODA OCTAVIA 1.6TDI 110HK 6VXL 4WD 5DR CBI DIESEL FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	12.686 A
4951 7714	W1003847 995 SEK	VW Passat -17 Inter axle Rubber joint	VOLKSWAGEN PASSAT ALLTRACK 2.0TSI 220HK DSG 4WD 5DR FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	890 A
5015 7714	W992737 1.795 SEK	Volvo V60 Cross Country -20 Inter axle Rubber joint	V60 CC AUT D4 2.0 140KW D4 D420AT14 AUT TG-81SC AWD SVÄNGNINGSDÄMPARE AOC	Norrbottns Bildemontering AB 0929-70000	2.636 A
1540 7714	W987712 395 SEK	BMW 5-Series -16 Inter axle Rubber joint	BMW 520D XDRIVE 2.0D XDRIV 190H TIPTRONIC 4WD 5DR C HARDY-SKIVA	Norrbottns Bildemontering AB 0929-70000	15.938 A
1540 7714	W987711 395 SEK	BMW 5-Series -16 Inter axle Rubber joint	BMW 520D XDRIVE 2.0D XDRIV 190H TIPTRONIC 4WD 5DR C HARDY-SKIVA	Norrbottns Bildemontering AB 0929-70000	15.938 A
1511 7714	W975673 300 SEK	BMW X3 -15 Inter axle Rubber joint	BMW X3 XDRIVE 2.0D B47-D20A AUT 4WD 5DR SUV DIESEL	Norrbottns Bildemontering AB 0929-70000	9.947 A
4908 7714	W968719 600 SEK	VW Golf, e-Golf -11 Inter axle Rubber joint	VOLKSWAGEN GOLF 1.6TDI 6VXL 4WD 5DR CBI DIESEL FRÄMRE	Norrbottns Bildemontering AB 0929-70000	18.449 A
3343 7714	W960156 490 SEK	Mercedes E-Class 96->> -12 Inter axle Rubber joint	MERCEDES-BENZ 212 E 200 CDI 2.2CDI 136HK 6VXL 4DR S	Norrbottns Bildemontering AB 0929-70000	9.601 A
4951 7714	W937438 995 SEK	VW Passat -17 Inter axle Rubber joint	VOLKSWAGEN PASSAT 2.0TDI 190HK DSG 4WD 4DR SED DIES FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	3.294 A
4207 7714	W909496 695 SEK	Skoda Superb -13 Inter axle Rubber joint	SKODA SUPERB 2.0TDI 140HK DSG 4WD 5DR CBI DIESEL FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	11.104 A
4207 7714	W898929 695 SEK	Skoda Superb -13 Inter axle Rubber joint	SKODA SUPERB CFFB A 5DR CBI DIESEL FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	12.613 A
4929 7714	W894587 695 SEK	VW Passat -13 Inter axle Rubber joint	VOLKSWAGEN PASSAT ALLTRACK CFGB A 5DR CBI DIESEL LAMELL FRAM	Norrbottns Bildemontering AB 0929-70000	14.750 A
4984 7714	W894159 800 SEK	VW Tiguan -14 Inter axle Rubber joint	VOLKSWAGEN TIGUAN 2.0TDI 177HK TIPTRONIC 4WD 5DR SU FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	10.937 A
4207 7714	W893571 695 SEK	Skoda Superb -11 Inter axle Rubber joint	SKODA 3T 2.0TDI 170HK 6VXL 4WD 4DR CBI DI FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	4.273 A
4984 7714	W892738 800 SEK	VW Tiguan -13 Inter axle Rubber joint	VOLKSWAGEN TIGUAN 2.0TSI R4 180HK DSG 5DR SUV BENSI FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	6.255 A
4951 7714	W885302 995 SEK	VW Passat -15 Inter axle Rubber joint	VOLKSWAGEN PASSAT 4M BLUEMOTIO 2.0TDI 190HK DSG 4WD FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	116 A
4951 7714	W884730 995 SEK	VW Passat -16 Inter axle Rubber joint	VOLKSWAGEN PASSAT 4M BLUEMOTIO 2.0TDI 150HK 6VXL 4W FRÄMRE LAMELL	Norrbottns Bildemontering AB 0929-70000	543 A

VCode PCode	Stock no. Price	Vehicle Part	Vehicle Information Part Information	Company Phone	Milage Quality
4949 7714	W875741 995 SEK	VW Golf, e-Golf -17 Inter axle Rubber joint	VW GOLF ALLTRACK 1.8TSI 1.8TSI 180HK DSG 4DR CBI BE FRAM LAMELL	Norrbottens Bildemontering AB 0929-70000	271 A
3343 7714	W867464 550 SEK	Mercedes E-Class 96->> -15 Inter axle Rubber joint	MERCEDES-BENZ 212 K E 250 BLUE 2.2CDI 204HK TIPTRON	Norrbottens Bildemontering AB 0929-70000	8.748 A
4209 7714	W866838 795 SEK	Skoda Octavia -15 Inter axle Rubber joint	OCTAVIA 1.6TDI R4 105HK 6VXL 5DR CBI DIESEL FRÄMRE LAMELL	Norrbottens Bildemontering AB 0929-70000	6.484 A
4207 7714	W865706 695 SEK	Skoda Superb -14 Inter axle Rubber joint	SKODA SUPERB 2.0TDI R4 170HK DSG 5DR CBI DIESEL FRÄMRE LAMELL	Norrbottens Bildemontering AB 0929-70000	5.991 A
4951 7714	W862537 995 SEK	VW Passat -16 Inter axle Rubber joint	VOLKSWAGEN PASSAT ALLTRACK 2.0TDI 239HK DSG 4WD 5DR FRÄMRE LAMELL	Norrbottens Bildemontering AB 0929-70000	12 A
4209 7714	W854404 2.375 SEK	Skoda Octavia -14 Inter axle Rubber joint	SKODA OCTAVIA 1.6TDI 105HK 6VXL 4WD 5DR CBI DIESEL BAKRE KOPPLINGSSKIVA MED UTJÄMNINGSVIKT	Norrbottens Bildemontering AB 0929-70000	8.522 A