

Stock no.:

W428750

Pris saknas

Shipping price / Shipping time:

- / 1-3 days

Vimmerby Bildemontering AB

Källnäs 110

59872 Södra Vi

Tel.: 0492-20028

Fax: 0492-20720

www.vimmerbybildemontering.se



Part - Hub rear

Stock no.:	Position:	Quality:	Fits fr./to m.y
W428750	Rear	A	-

New code:	Manufacturer:	Manufacturer no.:	Original no.:
-	-	-	-

Description:

Testad, OK! Vänster, Med ABS givare

Vehicle - Citroen C1

Chassi no.:	Model year:	Milage:	Fuel:
VF7PNCFAC89180593	2008	6.573	Bensin

Colour:	Colour code:	Interior:	Interior code:
MGRÅ	-	-	-

Gearbox:	Gearbox no.:	Gearbox ratio:	Group code:
5vxl	-	-	-

Engine:	Engine code:	Manufacturing date:	Registration date:
1,0i/CFA	CFA	200710	2007-10-12

Description:

1.0I SX 68HK 1,0I/CFA 5VXL 5DR CC BENSIN



Direct link: <http://www.bildelsbasen.se/141-W428750.html>